
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av vevaxel

GÄLLER: Motorer angivna i bifogad kopia av FAA AD 2000-23-21

ÅTGÄRD: Utför åtgärder angivna i FAA AD 2000-23-21

TID FÖR ÅTGÄRD: Inom 10 flygtimmar räknat från detta LVD's beslutsdatum, om ej tidigare utfört

UNDERLAG: TCM Mandatory Service Bulletin (MSB) 00-5C daterad den 10 oktober 2000

REFERENS: FAA AD 2000-23-21

BESLUTSDATUM: 14 december 2000

LFS 2000:137

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation
**Federal Aviation
Administration**

We post ADs on the internet at "av-info.faa.gov"

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Title 14 of the Code of Federal Regulations (14 CFR) part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety and are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (reference 14 CFR part 39, subpart 39.3).

2000-23-21 Teledyne Continental Motors: Amendment 39-11994. Docket 2000-NE-16-AD.
Supersedes Emergency AD 2000-08-51. Docket 2000-NE-16-AD.

Applicability

This Airworthiness Directive (AD) is applicable to Teledyne Continental Motors (TCM) IO-360, TSIO-360, LTSIO-360, O-470, IO-470, TSIO-470, IO-520, TSIO-520, LTSIO-520, IO-550, TSIO-550 and TSIOL-550 series reciprocating engines that were assembled, rebuilt, or overhauled using a crankshaft that was manufactured between April 1, 1998, and March 31, 2000, listed by engine and crankshaft serial number (SN) in TCM Mandatory Service Bulletin (MSB) 00-5C, dated October 10, 2000.

Note 1: The engines and crankshafts that are the subject of this AD were manufactured by TCM from April 1, 1998 through March 31, 2000. However the dates that the engines and crankshafts were delivered may not coincide with their dates of manufacture. For crankshafts identified in paragraph (a) of this AD, TCM has already determined which engines have a new suspect crankshaft installed and have identified those engines by engine SN. The crankshaft SN is only used to determine the need for taking a core sample for those crankshafts identified in paragraph (a) and (b) of this AD. The engine SN can be found in logbooks or other maintenance records. For those engines that were overhauled in the field with factory new crankshafts, the crankshaft SN should be shown in work orders, log books or other maintenance records. If the engine was assembled new, rebuilt, or overhauled on or before March 31, 1998, or on or after April 1, 2000, no action is required.

Note 2: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with the requirements of this AD is required within the next 10 hours time-in-service from the effective date of this AD, unless already done.

To prevent crankshaft connecting rod journal fracture, which could result in total engine power loss, in-flight engine failure and possible forced landing, do the following:

Note 3: TCM supplies an instructional video in the tool kit for MSB 00-5C. It is recommended that the technician views and understands "Instructional Video for Compliance with Teledyne Continental Motors Mandatory Service Bulletin MSB 00-5C" before performing these procedures.

Crankshaft Material Inspection

(a) For those engines and crankshafts listed by SN in TCM MSB 00-5C, dated October 10, 2000, do the crankshaft material inspection (crankshaft propeller flange core sample) as follows:

Note 4: The engine SN's listed in TCM MSB 00-5C contain only the numerical portion of the SN. Engines that have been rebuilt by TCM will have a letter "R" at the end of the six digit numerical portion. Disregard the letter "R."

(1) Do the crankshaft material inspection (crankshaft propeller flange core sample) in accordance with sections A through J of TCM MSB 00-5C, dated October 10, 2000, as follows:

(i) Use the specialized tools and equipment provided by TCM as listed in section A of TCM MSB 00-5C, dated October 10, 2000.

(ii) You may use each rotobroach bit to obtain up to six core samples. Replace the rotobroach after the sixth core sample, or before if the rotobroach does not cut with the maximum torque applied.

(iii) Maintain a record of each core sample obtained with each rotobroach bit used. Contact TCM to obtain additional rotobroach bits.

(iv) Do not exceed the torque limits specified in TCM MSB 00-5C, dated October 10, 2000, when obtaining the core sample.

(2) After obtaining the results of the core sample evaluation, disposition the crankshaft as follows:

(i) If TCM notifies you that the crankshaft is not serviceable, replace the crankshaft with a serviceable crankshaft of the same part number before further flight.

(ii) If TCM notifies you that the crankshaft is serviceable, the propeller assembly may be reinstalled.

Installation of Crankshafts

(b) After the effective date of this AD, do not install a crankshaft with a SN that is listed in MSB 00-5C, dated October 10, 2000, unless core samples have been taken and TCM has approved it for return to service.

(c) Crankshaft material inspections (crankshaft propeller flange core samples) that were done using TCM MSB 00-5, dated April 14, 2000; MSB 00-5A, dated April 28, 2000; or MSB 00-5B, dated May 25, 2000, comply with this AD and must not be repeated.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 5: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Atlanta ACO.

Incorporation by Reference Material

(e) The actions required by this AD shall be performed in accordance with Teledyne Continental Motors MSB 00-5C, dated October 10, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Teledyne Continental Motors, PO Box 90, Mobile, AL 36601; telephone toll free

1-888-200-7565, or on the TCM internet site "www.tcmlink.com". Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Effective Date of This AD

(f) This amendment becomes effective on December 12, 2000.

FOR FURTHER INFORMATION CONTACT: Jerry Robinette, Senior Engineer, Propulsion, Atlanta Aircraft Certification Office, FAA, Small Airplane Directorate, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, GA 30349; telephone: (770) 703-6096, fax: (770) 703-6097.

Issued in Burlington, Massachusetts, on November 13, 2000.

David A. Downey, Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.