
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll / byte av "Blade Grip"

GÄLLER: Bell 47G och 47J enligt bifogad kopia av FAA AD 91-20-10.

ÅTGÄRD: För att undvika brott i "Blade Grip" och orsaka manöversvårighet utför kontroll av S/N och eventuellt byte av "Blade Grip" enligt FAA AD 91-20-10.

TID FÖR ÅTGÄRD: Inom 50 flygtimmar räknat från detta LVD's utgivningsdatum.

UNDERLAG: FAA AD 91-20-10 eller senare utgåva.

REFERENS: FAA AD 91-20-10.

UTGIVNINGS-DATUM: 1991-12-12

LFS: 1991:32

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRWORTHINESS DIRECTIVE

AVIATION STANDARDS NATIONAL FIELD OFFICE
P.O. BOX 26460
OKLAHOMA CITY, OKLAHOMA 73125

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Federal Aviation Regulations, Part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety. They are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (FAR 39.3).

91-20-10 BELL HELICOPTER TEXTRON, INC.: Amendment 39-8044.
Docket No. 90-ASW-11.

Applicability: All Model 47G2, 47G2A, 47G2A1, 47G3, 47G3B1, 47G3B2, 47G3B2A, 47G4, 47G4A, 47G5, 47G5A, 47J, 47J2, and 47J2A helicopters, certificated in any category, with main rotor (M/R) grip part number (P/N) 47-120-252-11, installed.

Compliance: Required within the next 50 hours' time in service after the effective date of this AD, unless already accomplished.

To prevent failure of the M/R grip, which could result in loss of control of the helicopter, accomplish the following:

(a) Visually inspect the M/R grip and determine if one of the following serial numbers is installed:

IT- 0251, 0253, 0254, 0255, 0256, 0257, 0260, 0261, 0262, 0263, 0264, 0265, 0267, 0268, 0270, 0271, 0272, 0273, 0274, 0275, 0276, 0277, 0278, 0279, 0280, 0281, 0282, 0284, 0285, 0286, 0289, 0290, 0291, 0293, 0294, 0295, 0296, 0297, 0299, 0300, 0302, 0303, 0306, 0308, 0312, 0313, 0315, 0316, 0317, 0319, 0323, 0324, 0326, 0327, 0328, 0329, 0330, 0333, 0334, 0335

ITM- 0005, 0007, 0022, 0046, 0077, 0096, 0109, 0112, 0114, 0115, 0125, 0128, 0133, 0155, 0161, 0165, 0166, 0167, 0168, 0170, 0171, 0178, 0182, 0183, 0185, 0187, 0189, 0191, 0192, 0194, 0197, 0198, 0202, 0204, 0211, 0212, 0218, 0234, 0235, 0236, 0237, 0238, 0239, 0240, 0241, 0242, 0243, 0244, 0245, 0246, 0248, 0249, 0250, 0251, 0252, 0253, 0255, 0256, 0257, 0258, 0259, 0261, 0262, 0263, 0264, 0265, 0266, 0267, 0269, 0270, 0271, 0272, 0273, 0274, 0275, 0276, 0277, 0278, 0279, 0280, 0281, 0282, 0283, 0284, 0286, 0287, 0288, 0289, 0290, 0291, 0292, 0293, 0294, 0295, 0296, 0297

(b) If one of the M/R grips listed in paragraph (a) is installed, remove and replace with a serviceable part.

(c) An alternate method of compliance or adjustment of the compliance times, which provides an equivalent level of safety, may be used if approved by the Manager, Rotorcraft Certification Office, Federal Aviation Administration, Fort Worth, Texas 76193-0170, telephone (817) 624-5170.

NOTE: If any of the M/R grips identified in paragraph (a) are found, either installed or as spares, the FAA recommends that the parts be permanently marked or defaced so that they cannot be misconstrued as airworthy.

This amendment (39-8044, AD 91-20-10) becomes effective on November 14, 1991.

FOR FURTHER INFORMATION CONTACT:

Mr. Gary B. Roach, Rotorcraft Directorate, Rotorcraft Certification Office, ASW-170, FAA, Southwest Region, Fort Worth, Texas 76193-0170, telephone (817) 624-5179.