

Sektion 2. Utlandstillverkad flygmateriel

**TITEL:** Kontroll / byte av nödventil för bränslesystemets ventilationsledning

**GÄLLER:** Model 369D, 369E (S/N 001E t o m 0508E) 369F (S/N 0003 t o m 0091) 369FF (S/N 0003 t o m 0091) och 369H med installerad nödventil P/N 369H8108, 369H8108-501 eller 369H8108-503.

**ÅTGÄRD:** Utför åtgärder angivna i bifogad kopia av FAA AD 93-18-05.

**TID FÖR ÅTGÄRD:** Vid tider och intervaller angivna i bifogad kopia av FAA AD 93-18-05.

**UNDERLAG:** FAA AD 93-18-05  
McDonnell Douglas Helicopter Company Service Information Notice HN-234, DN-181, EN-73, FN-60 daterad 17 januari 1992 eller senare utgåva.

**REFERENS:** FAA AD 93-18-05

**UTGIVNINGS-DATUM:** 1993-12-16

**LFS: 1993:41**

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.



## AIRWORTHINESS DIRECTIVE

FLIGHT STANDARDS SERVICE  
REGULATORY SUPPORT DIVISION  
P.O. BOX 26460  
OKLAHOMA CITY, OKLAHOMA 73125-0460

U.S. Department  
of Transportation  
Federal Aviation  
Administration

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Federal Aviation Regulations, Part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety and are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (reference FAR Subpart 39.3).

**93-18-05 MCDONNELL DOUGLAS HELICOPTER COMPANY and HUGHES HELICOPTERS, INC.:** Amendment 39-8690. Docket Number 92-ASW-33.

Applicability: Model 369D, 369E (Serial No. 0001E thru 0508E), 369F (Serial No. 0003 thru 0091), 369FF (Serial No. 0003 thru 0091), and 369H series helicopters, equipped with fuel vent line emergency shutoff valve assemblies, part number (P/N) 369H8108, 369H8108-501 or 369H8108-503, certificated in any category.

Compliance: Helicopters with less than 2,400 hours' time-in-service on the effective date of this AD shall be inspected on or before attaining 2,500 hours' time-in-service, and thereafter, at an interval not to exceed 100 hours' time-in-service from the last inspection until an improved fuel vent line emergency shutoff valve assembly (assembly) is installed in accordance with paragraph (d) of this AD. Helicopters with 2,400 hours' or more time-in-service on the effective date of this AD shall be inspected in accordance with this AD within the next 100 hours' time-in-service, and thereafter, at an interval not to exceed 100 hours' time-in-service from the last inspection until an improved assembly is installed in accordance with paragraph (d) of this AD.

To prevent erroneously high inflight fuel quantity indications due to a blocked fuel vent line in the assembly, accomplish the following:

(a) Remove the assembly from the helicopter as required by the appropriate Model 369 maintenance manual.

(b) Inspect the fuel vent line emergency shutoff valve (valve) in accordance with Part I, Fuel Vent Line Emergency Shutoff Valve Inspection, of McDonnell Douglas Helicopter Company Service Information Notice HN-234, DN-181, EN-73, FN-60, dated January 17, 1992.

(c) If the inspections conducted in accordance with the requirements of paragraph (b) uncover an incorrectly closed or obstructed valve, before further flight install an airworthy assembly in accordance with the appropriate Model 369 maintenance manual.

(d) Install assembly, P/N 369H8108-505 or higher dash number, as follows, unless already accomplished:

(1) For helicopters with 2,400 hours' or more time-in-service on the effective date of this AD, install the assembly on or before attaining the next 600 hours' time-in-service.

(2) For helicopters with less than 2,400 hours' time-in-service on the effective date of this AD, install the assembly before attaining 3,000 hours' time-in-service.

(e) An alternative method of compliance or adjustment of the compliance time, which provides an acceptable level of safety, may be used when approved by the Manager, Propulsion Branch, Los Angeles Aircraft Certification Office, 3229 E. Spring Street, Long Beach, California 90806-2425. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Propulsion Branch, Los Angeles Aircraft Certification Office.

NOTE: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, Propulsion Branch, Los Angeles Aircraft Certification Office.

(f) Special flight permits may be issued in accordance with FAR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(g) The inspection shall be done in accordance with MDHC Service Information Notice HN-234, DN-181, EN-73, FN-60, dated January 17, 1992. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR Part 51. Copies may be obtained from McDonnell Douglas Helicopter Company, 5000 East McDowell Road, Mesa, Arizona 85205-9797, Attention: Field Service Department. Copies may be inspected at the FAA, Office of the Assistant Chief Counsel, 4400 Blue Mound Road, bldg 3B, room 158, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective December 21, 1993.

**FOR FURTHER INFORMATION CONTACT:**

Mr. Bruce Conze, Aerospace Engineer, Propulsion Branch, Los Angeles Aircraft Certification Office, ANM-143L, FAA, Northwest Mountain Region, 3229 E. Spring Street, Long Beach, California 90806-2425, telephone (310) 988-5261, fax (310) 988-5210.