

Sektion 2. Utlandstillverkad flygmateriel

TITEL: Inspektion av främre vingkoppelspantets liv för sprickor

GÄLLER: Beech modeller angivet i bifogad kopia av FAA AD 95-04-03.

ÅTGÄRD: För att undvika spricktillväxt som kan äventyra strukturintegriteten av vinginfästningen, utför åtgärder enligt bifogad kopia av FAA AD 95-04-03. Rapportera dock eventuella sprickor till Luftfartsinspektionen.

TID FÖR ÅTGÄRD: Vid 1500 flygtimmar eller inom 100 flygtimmar vilket som inträffar senast och i intervaller därefter enligt kopia av FAA AD 95-04-03, räknat från detta LVD:s utgivningsdatum.

UNDERLAG: Beech SB No 2360, daterad November 1990 eller senare utgåva.
FAA AD 95-04-03.

REFERENS: FAA AD 95-04-03.

UTGIVNINGSDATUM: 1995-04-06

LFS: 1995:20

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

AIRWORTHINESS DIRECTIVE

FLIGHT STANDARDS SERVICE
 REGULATORY SUPPORT DIVISION
 P.O. BOX 26460
 OKLAHOMA CITY, OKLAHOMA 73125-0460

U.S. Department
 of Transportation
**Federal Aviation
 Administration**

The following Airworthiness Directive issued by the Federal Aviation Administration in accordance with the provisions of Federal Aviation Regulations, Part 39, applies to an aircraft model of which our records indicate you may be the registered owner. Airworthiness Directives affect aviation safety and are regulations which require immediate attention. You are cautioned that no person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of the Airworthiness Directive (reference FAR Subpart 39.3).

95-04-03 BEECH AIRCRAFT CORPORATION: Amendment 39-9155; Docket No. 94-CE-12-AD.
 Supersedes AD 92-08-07, Amendment 39-8218.

Applicability: The following model and serial number airplanes, certificated in any category:

Models	Serial Numbers
35-33, 35-A33, 35-B33, 35-C33, E33, F33, and G33	CD-1 through CD-1304
35-C33A, E33A, and F33A	CE-1 through CE-1192
E33C and F33C	CJ-1 through CJ-179
H35, J35, K35, M35 N35, P35, S35, V35, V35A, and V35B	D-4866 through D-10403
36 and A36	E-1 through E-2397
A36TC and B36TC	EA-1 through EA-471

Compliance: Required initially with whichever of the following is applicable, and thereafter as indicated:

- o Upon the accumulation of 1,500 hours time-in-service (TIS) or within the next 100 hours TIS after the effective date of this AD, whichever occurs later, unless already accomplished;
- o Within 500 hours TIS after the inspection required by superseded AD 92-08-07, Amendment 39-8218, or within the next 100 hours TIS after the effective date of this AD, whichever occurs later; or
- o Within 500 hours TIS after the last inspection required by AD 91-14-13, Amendment 39-7054 (superseded by AD 92-08-07), or within the next 100 hours TIS, whichever occurs later.

To prevent spar carry-through frame structure failure, which, if not detected and corrected, could result in severe structural damage to the wing, accomplish the following:

(a) Inspect the wing front spar carry-through frame (web) structure for cracks in accordance with the instructions in Beech Service Bulletin (SB) No. 2360, dated November 1990. Repair or reinforce any cracked wing front spar carry-through frame structure and reinspect as specified in the paragraphs that follow.

(b) If no cracks are found, reinspect as specified in paragraph (a) of this AD at intervals not to exceed 500 hours TIS as long as no cracks are found. When cracks are found, repair or reinforce the wing front spar carry-through frame structure and reinspect as specified in this AD.

(c) If cracks are found in the bend radius and not in the web face in the areas of the huckbolt fasteners during the inspection specified in paragraph (a) of this AD, accomplish the following at the time specified in accordance with the instructions in Beech SB No. 2360:

(1) For cracks up to 2.25 inches, accomplish one of the following, as applicable:

(i) If not more than one crack on either side of the wing forward spar carry-through frame structure bend radius is found, prior to further flight, stop drill each crack at the crack ends. Within the next 200 hours TIS and thereafter at intervals not to exceed 200 hours TIS, reinspect each crack for progression and repair accordingly. Upon the installation of the applicable P/N 36-4004 Kit, extend the repetitive inspection time to 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) If more than one crack is found on either side of the wing forward spar carry-through frame structure bend radius, prior to further flight, install the applicable Beech P/N 36-4004 Kit, reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(2) For cracks between 2.25 and 4.0 inches, accomplish one of the following, as applicable:

(i) If not more than one crack on either side of the wing forward spar carry-through frame structure bend radius is found, prior to further flight, stop drill each crack at the crack ends, and within the next 100 hours TIS, install the applicable Beech P/N 36-4004 Kit. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) If more than one crack is found on either side of the wing forward spar carry-through frame structure bend radius, prior to further flight, install the applicable P/N 36-4004 Kit, and reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(3) For cracks exceeding 4.0 inches, prior to further flight, install the applicable Beech P/N 36-4004 Kit, reinspect at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(d) If cracks are found in the web face in the area of the huckbolt fasteners but not in the bend radius during the inspections specified in paragraph (a) of this AD, accomplish the following at the time specified in accordance with the instructions in Beech SB No. 2360, but do not stop drill the cracks because it is possible to damage the structure behind the web face:

(1) For cracks less than 1.0 inch in length, accomplish one of the following, as applicable:

(i) If not more than one crack on either side of the wing forward spar carry-through frame structure web face is found, within the next 200 hours TIS and thereafter at intervals not to exceed 200 hours TIS, reinspect each crack for progression and repair accordingly. Upon the installation of the applicable P/N 36-4004 Kit, extend the repetitive inspection time to 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) If more than one crack is found on either side of the wing forward spar carry-through frame structure web face, prior to further flight, install the applicable Beech P/N 36-4004 Kit, reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(2) For cracks more than 1.0 inch in length, accomplish one of the following, as applicable:

(i) If not more than one crack on either side of the wing forward spar carry-through frame structure web area is found, within the next 25 hours TIS, install the applicable Beech P/N 36-4004 Kit. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) If more than one crack is found on either side of the wing forward spar carry-through frame structure bend radius, prior to further flight, install the applicable Beech P/N 36-4004 Kit, reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(3) If a crack passes through two fasteners but is less than 0.5 inches beyond either fastener, accomplish one of the following, as applicable:

(i) If not more than one crack on either side of the wing forward spar carry-through frame structure web area is found, within the next 25 hours TIS, install the applicable Beech P/N 36-4004 Kit, reinspect at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) If more than one crack is found on either side of the wing forward spar carry-through frame structure bend radius, prior to further flight, install the applicable Beech P/N 36-4004 Kit, reinspect at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(4) If a crack passes through two fasteners but is more than 0.5 inches beyond either fastener, prior to further flight, install the applicable Beech P/N 36-4004 Kit. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(e) If cracks are found in both the web face in the area of the huckbolt fasteners and the bend radius during the inspections required in paragraph (a) of this AD, accomplish the following in accordance with the instructions in Beech SB No. 2360:

(1) If only one crack is found on either side of the airplane, prior to further flight, repair each crack in accordance with the criteria and instructions in paragraphs (c)(1) through (c)(3) or (d)(1) through (d)(4) of this AD, as applicable. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(2) If more than one crack is found on either side of the airplane, accomplish one of the following as applicable:

(i) For any crack that is 1.0 inch or more in length, prior to further flight, install the applicable Beech P/N 36-4004 Kit. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(ii) For any crack under 1.0 inch in length, within the next 200 hours TIS and thereafter at intervals not to exceed 200 hours TIS, reinspect each crack for progression and repair accordingly. Upon the installation of the applicable P/N 36-4004 Kit, extend the repetitive inspection time to 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(f) If a fuselage skin crack is found around the opening of the lower forward carry-through fitting, prior to further flight, obtain repair instructions from the manufacturer through the Wichita Aircraft Certification Office (ACO) at the address specified in paragraph (h) of this AD, and incorporate these instructions. Reinspect thereafter at intervals not to exceed 500 hours TIS, and repair or reinforce any cracked wing front spar carry-through frame structure as specified in this AD.

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(h) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Wichita ACO, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

NOTE: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(i) The inspections required by this AD shall be done in accordance with No. 2360, dated November 1990. This incorporation by reference was previously approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from the Beech Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(j) This amendment (39-9155) supersedes AD 92-08-07, Amendment 39-8218.

(k) This amendment becomes effective on April 7, 1995.

FOR FURTHER INFORMATION CONTACT:

Mr. Larry Engler, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4122; facsimile (316) 946-4407.