
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Sprickkontroll av huvudrotorväxelns tvärbalk

GÄLLER: AS 350 versionerna B, BA, B1, B2 och D med installerad tvärbalk P/N 350A38.1018.

ÅTGÄRD: Utför åtgärder angivna i EUROCOPTER FRANCE AS 350 Telex Service No 05.00.28.

TID FÖR ÅTGÄRD: Inom tider angivna i bifogad kopia av DGAC AD 96-156-071(B)R1 räknat från detta LVD's utgivningsdatum.

UNDERLAG: EUROCOPTER FRANCE Telex Service No 05.00.28
DGAC AD 96-156-071(B)R1

REFERENS: DGAC AD 96-156-071(B)R1

BESLUTSDATUM: 1997-06-25

LFS 1997:31

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this**Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

ref.: 96-156-071(B) R1

In case of any difficulty, reference should
be made to the French original issue.**EUROCOPTER FRANCE****AS 350 Helicopters****MGB Suspension Bi-directional Cross Beam**

This Airworthiness Directive applies to AS 350 helicopters, versions B, BA, B1, B2 and D fitted with a MGB suspension bi-directional cross beam P/N 350A38.1018 - all dash numbers, installed on the complete cross beam assemblies P/No 350A38.0210 - all dash numbers (which are not modified per MOD. 072720).

Further to the discovery, in service, of cracks in the suspension cross beam, the following measures are rendered mandatory :

1. Cross beams that have logged at least 2000 flying hours or 10 000 cycles :

- 1.1. Within 30 flying hours from the effective date of the original issue of this Airworthiness Directive, and then at intervals of no more than 30 flying hours or 150 cycles (whichever limit is reached first), visually check the cross beam for cracks, in accordance with the instructions given in paragraph 2B(1) of the referenced EUROCOPTER FRANCE Service Bulletin N° 05.00.28 and apply the necessary measures.

- 1.2. Each time the cross beam or the MGB is removed, irrespective of whether the removal was scheduled or not, comply with paragraph 2B(2) of the referenced Service-Bulletin.

2. For cross beams that have logged more than 5000 flying hours and which have not been checked during or since the last major inspection as per paragraph 2B(2) of the referenced Service Bulletin :

.../...

n/DJ

June 04, 1997

EUROCOPTER FRANCE
AS 350 Helicopters

96-156-071(B) R1