

# LUFTVÄRDIGHETSDIREKTIV (LVD)

A. Helikopter Eurocopter France LVD Nr 2835R4 Upphäver LVD 2835R3

Sektion 2. Utlandstillverkad flygmateriel

TITEL:

Kontroll av huvudrotorblad

**GÄLLER:** 

Eurocopter SE 3160, SA 316B, SA 316C, SA 319B och SA 315B

ATGÄRD:

Utför åtgärd enligt bifogade DGAC AD Nr 1998-170-056(A) R2 och

Nr 1998-171-039(A) R2. OBS Bilaga.

TID FÖR ÅTGÄRD:

Inom tider och intervaller angivna i punkt 3.1

**UNDERLAG:** 

Eurocopter SA 316/319 Service Bulletin No. 05.98 och Eurocopter SA

315 Service Bulletin No. 05.39

**REFERENS:** 

DGAC AD Nr 1998-170-056(A) R2 och Nr 1998-171-039(A) R2.

**BESLUTSDATUM:** 

2000-02-02

LFS 2000: 12

Atgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

**Postadress** 

Gatuadress

Telefonnummer

Telegram Civilair Telex

601 79 NORRKÖPING

Vikboplan 11

011-192000

Norrköping

62450

**GSAC** 

# **AIRWORTHINESS DIRECTIVE**

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref.: 1998-170-056(A) R2 In case of any difficulty, reference should be made to the French original issue.

# **EUROCOPTER**

## SA 316/319 helicopters

Main rotor blades - Cuff to spar assembly

## 1. APPLICABILITY

This Airworthiness Directive applies to SE 3160, SA 316B, SA 316C and SA 319B helicopters equipped with main rotor blades P/N:

3160S11-10000 all dash numbers, 3160S11-30000 all dash numbers,

3160S11-35000 all dash numbers, 3160S11-40000 all dash numbers,

3160S11-45000 all dash numbers, 3160S11-50000 all dash numbers,

3160S11-55000 all dash numbers.

#### 2. REASON

This Airworthiness Directive is issued subsequent to the failure of a main rotor blade on a SA 315 B helicopter.

#### 3. MANDATORY ACTION AND COMPLIANCE TIME

The following measures are mandatory:

- 3.1. Check the spar areas for cracks in accordance with the procedure defined in paragraph 2B of EUROCOPTER Service Bulletin No. 05.98 referenced below,
  - **3.1.1.** for blades which have logged less than 400 flying hours, at the latest when the blades reach 400 flying hours,
  - **3.1.2.** for blades which have logged 400 flying hours or more, and which have been checked in accordance with the original issue of this Airworthiness Directive or its Revision 1, within 25 flying hours following the last check carried out,
  - 3.1.3. for blades which have logged 400 flying hours or more, and which have not yet been checked, before the next flight following the effective date of Revision 2 of this Airworthiness Directive.

n/DJ

**GSAC** 1998-170-056(A) R2 **AIRWORTHINESS DIRECTIVE** ref.: Page n° 2 .../... 3.1.4. for blades which are held as spares, before they are installed on an aircraft, 3.1.5. if 1 Omega vibration suddenly occurs, before the next flight. 3.2. Repeat the check for cracks defined in paragraph 3.1. above, every 100 flying hours or 600 cycles (the first limit reached is applicable). (The definition of "cycle" is given in paragraph 1.D.2. of the Service Bulletin referenced below). 3.3. If a crack is detected, remove the blade from service. REF.: EUROCOPTER SA 316/319 Service Bulletin No. 05.98 ١ This Revision 2 replaces Airworthiness Directive 98-170-056(A) R1 dated May 06, 1998. **EFFECTIVE DATES:** Original AD: Upon receipt of Telegraphic diffusion from APRIL 14, 1998 **Revision 1** : Upon receipt of Telegraphic diffusion from APRIL 17, 1998 : Upon receipt from JANUARY 12, 2000 Revision 2

**GSAC** 

# **AIRWORTHINESS DIRECTIVE**

# released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref.: 1998-171-039(A) R2 In case of any difficulty, reference should be made to the French original issue.

# **EUROCOPTER**

# SA 315 helicopters

Main rotor blades - Cuff to spar assembly

# 1. APPLICABILITY

This Airworthiness Directive applies to SA 315 B helicopters, equipped with main rotor blades P/N:

3160S11-10000 all dash numbers, 3160S11-30000 all dash numbers,

3160S11-35000 all dash numbers, 3160S11-40000 all dash numbers,

3160S11-45000 all dash numbers, 3160S11-50000 all dash numbers,

3160S11-55000 all dash numbers.

#### 2. REASON

This Airworthiness Directive is issued subsequent to the failure of a main rotor blade on a SA 315 B helicopter.

#### 3. MANDATORY ACTION AND COMPLIANCE TIME

The following measures are mandatory:

- **3.1.** Check the spar areas for cracks in accordance with the procedure defined in paragraph 2B of EUROCOPTER Service Bulletin No. 05.39 referenced below,
  - **3.1.1.** for blades which have logged less than 400 flying hours, at the latest, when the blades reach 400 flying hours,
  - **3.1.2.** for blades which have logged 400 flying hours or more, and which have been checked in accordance with the original issue of this Airworthiness Directive or its Revision 1, within 25 flying hours following the last check carried out,
  - **3.1.3.** for blades which have logged 400 flying hours or more, and which have not yet been checked, before the next flight following the effective date of Revision 2 of this Airworthiness Directive.

n/DJ

Page n° 1998-171-039(A) R2 **GSAC** AIRWORTHINESS DIRECTIVE ref.: .../...

- 3.1.4. for blades which are held as spares, before they are installed on an aircraft,
- 3.1.5. if 1 Omega vibration suddenly occurs, before the next flight.
- 3.2. Repeat the check for cracks defined in paragraph 3.1. above, every 100 flying hours or 600 cycles (the first limit reached is applicable). (The definition of "cycle" is given in paragraph 1.D.2. of the Service Bulletin referenced below).
- 3.3. If a crack is detected, remove the blade from service.

REF.: EUROCOPTER SA 315 Service Bulletin No. 05.39.

This Revision 2 replaces Airworthiness Directive 98-171-039(A) R1 dated May 06, 1998.

# **EFFECTIVE DATES:**

Original AD: Upon receipt of Telegraphic

diffusion from APRIL 14, 1998

: Upon receipt of Telegraphic Revision 1

diffusion from APRIL 17, 1998

Revision 2 : Upon receipt from JANUARY 12, 2000