
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-040

AIRCRAFT TYPE: SAAB MFI 15-200 and SAAB MFI 15-200A

SERIAL No:s

AFFECTED: All

SUBJECT: Inspection and replacement of installation bolts for the Main landing gear.

BACKGROUND: It is reported 3 cases of damaged end surfaces of Main landing gear installation bolts which can cause unacceptable play between landing gear and the saddle.

REFERENCE

DOCUMENTS: Parts Catalog T:O: 1T-17-4, MFI 15 Maintenance Manual.

ACTIONS:

- A. Remove and check all 6 bolts according to Service Bulletin MB 15.057.
- B. Replace all 6 bolts

COMPLIANCE

TIME:

- A. At next 500 Flights Hours inspection
- B. At each 1000 Flights Hours inspection

Norrköping 1990-06-29

**LUFTFARTSVERKET
Flight Safety Department**

LFS:1990:22

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.