
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-041

AIRCRAFT TYPE: SAAB SF 340A (SAAB FAIRCHILD 340A) and SAAB 340B

SERIAL No:s

AFFECTED: SAAB SF 340A-079 through -159
SAAB 340B-160 through -199

SUBJECT: Correction of wire size in the autopilot electrical system

BACKGROUND: To prevent possible overload, if a short circuit occurs in the autopilot system, the wire FD 574-24 from 301VT BH:C to 203VU P33:A1, which is currently a 24 AWG wire, must be replaced with 20 AWG size wire.

REFERENCE

DOCUMENTS: SAAB-SCANIA AB Service Bulletin SAAB 340-34-068.

ACTIONS: Perform wire change in accordance with SAAB-SCANIA AB Service Bulletin SAAB-340-34-068 dated November 9, 1990, or later revision.

COMPLIANCE

TIME: To be accomplished no later than June 1, 1991

Norrköping 1990-11-23

LUFTFARTSVERKET
Flight Safety Department

LFS:1990:30

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.