
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Byte av elektriska enheter

GÄLLER: SA 360C och SA 365 C, C1, C2 och C3 alla S/N med installerade enheter tillverkade av "Connectral"

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 98-252-043 (A)

TID FÖR ÅTGÄRD: Inom 200 flygtimmar räknat från detta LVD's beslutsdatum

UNDERLAG: DGAC AD 98-252-043 (A)
Eurocopter SA 360 C och SA 365 C Service Bulletin No 01.37

REFERENS: DGAC AD 98-252-043 (A)

BESLUTSDATUM: 1998-08-04

LFS 1998:51

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-252-043(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

SA 360C and SA 365C Helicopters

Electrical Connection-Modules Manufactured by "CONNECTRAL"

1. EFFECTIVITY

This Airworthiness Directive applies to SA 360C and SA 365C, C1, C2 and C3 helicopters, equipped with electrical modules, all part numbers, manufactured by "CONNECTRAL".

- 1.1. If an optional item or an equipment item comprising an electrical circuit equipped with a module has been installed or replaced between April 17, 1995, and August 1, 1996.
- 1.2. If an electrical circuit has been modified with the installation or replacement of a module between April 17, 1995, and August 1, 1996.

2. REASON

This Airworthiness Directive is issued following the discovery of malfunctions due to faulty CONNECTRAL modules on the electrical circuits of a Super Puma AS 332 helicopter.

3. MANDATORY MEASURES AND COMPLIANCE DUE DATE

- 3.1. Within 200 flying hours from the effective date of this Airworthiness Directive, and at the latest by December 31, 1998 comply with the instructions given in paragraph 2 of EUROCOPTER SA 360C and SA 365C, C1, C2 and C3 Service Bulletin n° 01.37 referenced below.
- 3.2. For CONNECTRAL modules held as spares (detail parts or installed on equipment) : comply with the instructions specified in paragraph 2A of referenced Service Bulletin before installing the modules, (identification of the CONNECTRAL modules and replacement of faulty modules).

Ref. : EUROCOPTER SA 360C and SA 365C Service Bulletin n° 01.37.

EFFECTIVE DATE : JULY 11, 1998

n/DJ

July 01, 1998	EUROCOPTER SA 360C and SA 365C Helicopters	98-252-043(A)
---------------	---	---------------