
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Livstidsbegränsning av stjärtrotorblad

GÄLLER: SE 3130, SE 313B, SA 3180, SA 318B och SA 318C med installerade blad enligt bifogad kopia av DGAC AD 1999-127-057(A) R1

ÅTGÄRD: Inför livstidsbegränsning 400 flygtimmar för rotorblad enligt DGAC AD 1999-127-057(A) R1

TID FÖR ÅTGÄRD: 2001-06-23

UNDERLAG: DGAC AD 1999-127-057(A) R1 och däri angivet underlag

REFERENS: DGAC AD 1999-127-057(A) R1

BESLUTSDATUM: 20 juni 2001

LFS 2001:79

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1999-127-057(A) R1
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

SA 313/318 helicopters

Limitation of tail rotor blade service life (ATA 05, 64)

1. EFFECTIVITY:

Helicopter models: SE 3130, SE 313B, SA 3180, SA 318B and SA 318C equipped with tail rotor blades
part number: 3160S34.11.000.00
serial numbers: 23484, 23485, 23486, 23487, 23488, 23489, 23490, 23491, 23492, 23493.

2. REASONS:

This AD is issued subsequent to the discovery of a non-compliance of blade cuff stems (blade-to-hub attachment) metallurgical structure affecting the service life of the 10 blades listed above.

Revision 1 of this AD covers the conversion of Service Telex No. 01.66 into Alert Service Bulletin (ASB) No. 01.66 with no change to the technical content.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

The service life of the blades listed above is limited to 400 hours from the effective date of the original Airworthiness Directive.

REF.: EUROCOPTER Alouette II and Alouette III Alert Service Bulletin No. 01.66.

This Revision 1 replaces AD 1999-127-057(A) dated April 07, 1999.

EFFECTIVE DATES:

Original AD : On receipt of the telegraphic AD
issued on MARCH 25, 1999

Revision 1 : JUNE 23, 2001

n/DJ

June 13, 2001

EUROCOPTER
SA 313/318 helicopters

1999-127-057(A) R1