

---

Sektion 2. Utlandstillverkad flygmateriel

---

**TITEL:** Modifiering av motorns urluftningssystem

**GÄLLER:** Alla Zlin 242L tillverkade av Moravan-Aeroplanes Inc. S/N t.o.m. 0730 och alla Zlin 143L S/N t.o.m. 0029 undantaget 0025 och 0027.

**ÅTGÄRD:** Utför åtgärder angivna i bifogad kopia av CAA-AD-042/1999

**TID FÖR ÅTGÄRD:** Vid nästa 100 timmars tillsyn men senast vid ordningsställande för vinteroperation.

**UNDERLAG:** Enligt underlag angivet i CAA-AD-042/1999 daterad 18 augusti 1999

**REFERENS:** CAA-AD-042/1999

**BESLUTSDATUM:** 1999-09-10

**LFS 1999:141**

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.


Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

|                   |              |               |                        |       |
|-------------------|--------------|---------------|------------------------|-------|
| Postadress        | Gatuadress   | Telefonnummer | Telegram               | Telex |
| 601 79 NORRKÖPING | Vikboplan 11 | 011-192000    | Civilair<br>Norrköping | 62450 |



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC

*Airport Ruzyne, 160 08 Prague 6*  
tel: 420-2-33320922, fax: 420-2-20562270



## AIRWORTHINESS DIRECTIVE

Number: CAA-AD-042/1999  
Supersedes: CAA-AD-2-012/96  
CAA-AD-2-012R1/96  
Date of issue: August 18, 1999  
MORAVAN-AEROPLANES Inc.  
Z 242L, Z 143L

### AIRCRAFT - ENGINE VENT LINE - MODIFICATION

- Applicability:** All Zlin 242L aircraft produced by Moravan-Aeroplanes Inc. Up to S/N 0730 incl., all Zlin 143L aircraft up to S/N 0029 incl., except S/N 0025 and 0027, certified in any category.
- Reason:** The following measures are rendered mandatory in order to prevent the oil leakage from the engine during cold weather operation (winter operation).
- Effective date:** October 7, 1999
- Compliance :** Engine vent adaptation of the Z 242L, Z 143L aircraft and corresponding revision of the Maintenance Manual of the Z 242L aircraft - Vol. I. in accordance with Mandatory Service Bulletin Z 242L/19a - Rev.3, Z 143L/20a at the next 100-hour inspection or at annual inspection, not later than at preparation for winter operation. Corresponding revision of the Flight Manual issued by the Mandatory Service Bulletin Z 242L/19a - Rev.2 remains effective.

*Remarks: - Where applicable, the requirements of this AD must be integrated into the Aircraft's Logbook(s).  
- Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 33320922, fax: 420 2 20562270.  
- Contact address for order Mandatory Service Bulletin: MORAVAN-AEROPLANES Inc. ZLIN Service, 765 81 OTROKOVICE, Czech Republic.*

Ing. Pavel MATOUŠEK  
Director of Airworthiness Division  
CAA CZ