
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Modifiering av utluftningsrör för motorns oljetank

GÄLLER: AS 350 versionerna B, B1, B2, BA, BB och D, vilka inte modifierats enligt Mod 07 2793.

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 2000-268-078(A).

TID FÖR ÅTGÄRD: Senast den 31 december 2000 om inte tidigare utfört.

UNDERLAG: EUROCOPTER AS 350 Service Bulletin No. 79.00.11 Rev. 1.

REFERENS: DGAC AD 2000-268-078(A)

BESLUTSDATUM: 21 juli 2000

LFS: 2000:96

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2000-268-078(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

AS 350 helicopters

Engine oil pipe - Fire proofing (ATA 79)

1. EFFECTIVITY:

AS 350 helicopters, versions: B, B1, B2, BA, BB and D on which MOD 07 2793 has not been embodied.

2. REASON:

This Airworthiness Directive is issued to render fireproofing of the engine oil tank breather pipe mandatory by fitting a heat-resistant silicone sheath.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

- 3.1. At the latest on December 31, 2000 (unless already done), protect the engine oil tank breather pipe using a protective sheath, in accordance with the instructions given in paragraph 2 of referenced EUROCOPTER AS 350 Service Bulletin No. 79.00.11 Rev. 1
- 3.2. From the effective date of this Airworthiness Directive, before installing an engine oil breather pipe on aircraft, comply with the instructions given in paragraph 2 of referenced Service Bulletin.

REF.: EUROCOPTER AS 350 Service Bulletin No. 79.00.11 Rev. 1

EFFECTIVE DATE : JULY 08, 2000

n/DJ

June 28, 2000

**EUROCOPTER
AS 350 helicopters**

2000-268-078(A)