
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av åtdragningsmoment för nosställets infästningsbultar

GÄLLER: TB 20 och TB 21 S/N 2001 t.o.m. 2006, 2008, 2010, 2012 och 2014

ÅTGÄRD: Utför åtgärder angivna i bifogad opia av DGAC AD 2001-001(A)

TID FÖR ÅTGÄRD: Inom 10 flygtimmar räknat från detta LVD's beslutsdatum

UNDERLAG: SB SOCATA TB No. BS 10-116-32

REFERENS: DGAC AD 2001-001(A)

BESLUTSDATUM: 17 januari 2001

LFS 2001:11

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-001(A)
In case of any difficulty, reference should be made to the French original issue.

SOCATA

TB 20 and TB 21 aircraft

Tightening of nose gear mount bolts (ATA 71)

1. APPLICABILITY:

The present Airworthiness Directive is applicable to TB20 and TB21 aircraft S/N 2001 through 2006, 2008, 2010, 2012 and 2014.

2. REASON:

It has been found that the nose gear mount attaching bolts may have been improperly tightened during production, from S/N 2001.

3. ACTIONS AND COMPLIANCE:

The following measures are made mandatory from the effective date of this Airworthiness Directive:

Within 10 flight hours, check and if necessary correct the tightening torque of the nose gear mount attaching bolts according to the instructions of SOCATA TB Service Bulletin No. BS 10-116-32.

Record the application of this Airworthiness Directive in the aircraft log book.

REF.: SB SOCATA TB No. 10-116-32 dated December 2000
(or later revisions).

EFFECTIVE DATE : JANUARY 20, 2001

n/JJD

January 10, 2001

SOCATA
TB 20 and TB 21 aircraft

2001-001(A)