
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-071

AIRCRAFT TYPE: SAAB 2000

SERIAL No:s

AFFECTED: Control Quadrant Saab P/N 7376100-531 (vendor P/N 43102-003),
Serial Number (S/N) 006-010, 013, 016, 017, 019 and 020.

SUBJECT: Engine Controls - Control Quadrant Replacement - Nuts on Power
Levers Applied with Loctite

BACKGROUND: Operators have reported two control quadrants with unusually high
friction in the power lever. The subsequent inspection showed that the
locking nuts in the lower part of the power lever were loose and caused
the high friction. This can cause jammed power lever.

**REFERENCE
DOCUMENTS:**

Saab Aircraft AB Service Bulletin SAAB 2000-76-003

ACTIONS: Replace the control quadrant with a modified control quadrant in
accordance with Saab Aircraft AB Service Bulletin SAAB 2000-76-003
dated 3 April, 1995 or later revision.

**COMPLIANCE
TIME:**

To be performed no later than 1 July, 1995.

**EFFECTIVE
DATE:**

12 April, 1995

LUFTFARTSVERKET
Flight Safety Department

LFS: 1995:23

The actions contained in this directive and reference document(s)
have been classified as mandatory for aircraft on Swedish register.