
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av bränslerör

GÄLLER: DR 400 modeller enligt DGAC AD 2001-034(A)

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 2001-034(A)

TID FÖR ÅTGÄRD: Enligt punkterna 3.1 och 3.2 i DGAC AD 2001-034(A)

UNDERLAG: ROBIN AVIATION Service Bulletin No 170, daterad den 3 juli 2000

REFERENS: DGAC AD 2001-034-(A)

BESLUTSDATUM: 29 januari 2001

LFS 2001:19

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-034(A)
In case of any difficulty, reference should be made to the French original issue.

ROBIN AVIATION

DR 400 aircraft

Fuel line pipes (ATA 28)

1. APPLICABILITY

This Airworthiness Directive concerns ROBIN AVIATION DR 400-120, DR 400-140B, DR 400-160, DR 400-180, DR 400-180R from serial number 2212 inclusive.

2. REASON

Deformation of fuel line pipes on each side of the fuel pump reported during maintenance could cause fuel leaks.

3. ACTIONS AND COMPLIANCE

3.1. The instructions required by Service Bulletin are rendered and must be performed within 50 flight hours after the effective date of the present Airworthiness Directive.

3.2. Re-inspect the fuel lines after 50 flight hours, and repeat this inspection every 500 flight hours.

Record application of this AD in the aircraft logbook.

REF.: ROBIN AVIATION Service Bulletin No. 170 dated July, 03, 2000.

EFFECTIVE DATE : FEBRUARY 03, 2001

n/OG

January 24, 2001

ROBIN AVIATION
DR 400 aircraft

2001-034(A)