
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll / byte av bromsoljebehållarens lock

GÄLLER: Alla modeller av DR, HR200 och R2000 enligt DGAC AD 2001-035(A)

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 2001-035(A)

TID FÖR ÅTGÄRD: Inom 10 flygtimmar räknat från detta LVD's beslutsdatum

UNDERLAG: ROBIN AVIATION Service Bulletin No 169, daterad den 3 juli 2000, eller senare utgåva

REFERENS: DGAC AD 2001-035(A)

BESLUTSDATUM: 30 januari 2001

LFS 2001:20

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-035(A)
In case of any difficulty, reference should be made to the French original issue.

ROBIN AVIATION

All DR models, HR 200 and R 2000 aircraft

Brake fluid reservoir cap (ATA 32)

1. APPLICABILITY

This Airworthiness Directive concerns the following ROBIN AVIATION aircraft (all serial numbers):

DR 400 all models,
DR 300 all models,
DR 200, DR 250, all models
DR 253 all models,
DR 220, DR 221 all models,
DR 100A, DR 105A, DR 1050, DR 1051 all models,
HR 200, R 2000 all types.

2. REASON

Non conforming cap found during servicing inspection.

3. ACTIONS AND COMPLIANCE

The instructions required by Service Bulletin are rendered mandatory and must be performed within 10 flight hours following the effective date of the present Airworthiness Directive.

Record application of this AD in the aircraft logbook.

REF.: ROBIN AVIATION Service Bulletin No. 169 dated July 03, 2000.

EFFECTIVE DATE : FEBRUARY 03, 2001

n/OG

January 24, 2001

ROBIN AVIATION
All DR models, HR 200 and R 2000 aircraft

2001-035(A)