
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av motorns luftintag

GÄLLER: Alla ROBIN modeller enligt DGAC AD 2001-036(A)

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av DGAC AD 2001-036(A)

TID FÖR ÅTGÄRD: Vid varje 100 timmars tillsyn eller varje år vilket som först inträffar

UNDERLAG: ROBIN AVIATION Service Bulletin No 174, daterad den 29 november 2000 eller senare utgåva

REFERENS: DGAC AD 2001-036(A)

BESLUTSDATUM: 29 januari 2001

LFS 2001:21

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-036(A)
In case of any difficulty, reference should be made to the French original issue.

ROBIN AVIATION

ROBIN aircraft all models

Engine air intake (ATA 75).

1. APPLICABILITY

This Airworthiness Directive concerns ROBIN aircraft all models all serial numbers except DR 400-500, DR 400-200R and R 2160i.

2. REASON

Fault reported in service following the presence of felt obstructing carburettor air intake.

3. MANDATORY ACTIONS AND COMPLIANCE

3.1. The referenced Service Bulletin instructions are rendered mandatory on the effective date of this Airworthiness Directive.

3.2. Repeat the inspection every 100 flight hours or every year, whichever occurs first.

Record application of this Airworthiness Directive in the aircraft logbook.

REF.: ROBIN AVIATION Service Bulletin No. 174 dated November 29, 2000.

EFFECTIVE DATE : FEBRUARY 03, 2001

n/OG

January 24, 2001

ROBIN AVIATION
ROBIN aircraft all models

2001-036(A)