
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll för eventuell elektrisk felkoppling

GÄLLER: Modeller och S/N angivna i bifogad kopia av DGAC AD 2001-263(A)

ÅTGÄRD: Utför åtgärder angivna i DGAC AD 2001-263(A)

TID FÖR ÅTGÄRD: Inom 60 flygtimmar räknat från beslutsdatum av detta LVD

UNDERLAG: Service Bulletin ROBIN AVIATION No.182 daterad 20 mars 2001

REFERENS: DGAC AD 2001-263(A)

BESLUTSDATUM: 6 juli 2001

LFS 2001:92

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-263(A)
In case of any difficulty, reference should be made to the French original issue.

ROBIN AVIATION

DR 400 aeroplanes

Battery and alternator circuit protectors (ATA 24)

1. APPLICABILITY

This Airworthiness Directive concerns ROBIN AVIATION aeroplanes DR 400/180 R No. 2207, DR 400/140 B No. 2211, DR 400/120 No. 2212, DR 400/180 No. 2216 and DR 400/160 No. 2220.

2. REASON

On the concerned aeroplanes, the battery and alternator circuit protectors may be inverted.

3. MANDATORY ACTIONS AND COMPLIANCE

The following measures are made mandatory from the effective date of this Airworthiness Directive :

Within the next 60 flight hours, check the battery and alternator circuit according to the instructions of ROBIN AVIATION referenced Service Bulletin.

Record application of this Airworthiness Directive in the Aircraft logbook.

REF.: Service Bulletin ROBIN AVIATION No. 182 dated March 20, 2001.

EFFECTIVE DATE : JULY 07, 2001

n/OG

June 27, 2001

ROBIN AVIATION
DR 400 aeroplanes

2001-263(A)