
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Modifiering av amperemätarens strömkrets.

GÄLLER: SOCATA TB9, TB10, TB20, TB200 och TB21 alla serienummer utrustade med amperemätare option OPT10 593 00M eller OPT 10 689 00M eller OPT 10 D689 00M.

ÅTGÄRD: Utför åtgärd enligt bifogad kopia av DGAC AD 2001-446(A)

TID FÖR ÅTGÄRD: Senast 31 december, 2001.

UNDERLAG: Service Bulletin SOCATA TB No. 10-122-24 daterad juli, 2001 eller senare utgåva.

REFERENS: DGAC AD 2001-446(A)

BESLUTSDATUM: 18 oktober 2001

LFS 2001:142

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram Civilair	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-446(A)
In case of any difficulty, reference should be made to the French original issue.

SOCATA

TB9, TB10, TB200, TB20 and TB21 aeroplanes

Ammeter circuit modification (ATA 24)

1. APPLICABILITY

The present Airworthiness Directive is applicable to TB aeroplanes all models and all serial numbers, equipped with the ammeter option ref. OPT 10 593 00M or OPT 10 689 00M or OPT 10 D689 00M.

2. REASON

Following the occurrence of an incident in service on an airplane equipped with the ammeter option, the electrical circuit is modified according to the technical prescriptions of referenced Service Bulletin SOCATA TB No. 10-122-24.

3. MANDATORY ACTIONS AND COMPLIANCE

The following measures are made mandatory from the effective date of this Airworthiness Directive:

At the next scheduled maintenance check and before December 31, 2001, modify the electrical circuit as indicated in the referenced Service Bulletin SOCATA TB No. 10-122-24.

Record the application of this Airworthiness Directive in the aircraft logbook.

REF.: Service Bulletin SOCATA TB No. 10-122-24 dated July 2001
(or later revisions)

EFFECTIVE DATE : OCTOBER 13, 2001

n/RH

October 03, 2001

SOCATA
TB9, TB10, TB200, TB20 and TB 21 aeroplanes

2001-446(A)