
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Borttagning av bygling.

GÄLLER: Eurocopter AS 350 modell B3 före införande av MOD 073146 med serienummer angivna i bifogad kopia av DGAC AD 2002-187-090(A).

ÅTGÄRD: Utför åtgärd enligt DGAC AD 2002-187-090(A).

TID FÖR ÅTGÄRD: Inom 100 flygtimmar räknat från 13 april 2002.

UNDERLAG: Eurocopter AS 350 Alert Service Bulletin No. 24.00.09.

REFERENS: DGAC AD 2002-187-090(A)

BESLUTSDATUM: 10 april 2002

LFS 2002:50

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2002-187-090(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

AS 350 helicopters

Electrical power (ATA 24)

1. EFFECTIVITY

AS 350 version B3 helicopters before embodiment of MOD 073146, with the following serial numbers:

3461, 3463, 3464, 3467, 3469, 3471, 3472, 3473, 3475, 3477, 3478, 3479, 3484, 3485, 3486, 3493, 3494, 3511 and 3522.

2. REASON

This Airworthiness Directive (AD) is issued further to a case of incorrect wiring resulting in an overloaded electrical power system that can cause disconnection of the generator and force the crew to terminate the flight under battery power.

3. MANDATORY ACTIONS AND COMPLIANCE TIME

Within the next 100 flight hours from the effective date of this Airworthiness Directive, remove the shunt and comply with the instructions given in paragraph 2 of referenced EUROCOPTER AS 350 Alert Service Bulletin No. 24.00.09.

REF.: EUROCOPTER AS 350 Alert Service Bulletin No. 24.00.09.

EFFECTIVE DATE : APRIL 13, 2002

n/DJ

April 03, 2002

EUROCOPTER
AS 350 helicopters

2002-187-090(A)