
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Felaktig installation av Horizontal Situation Indicator (HSI).

GÄLLER: Eurocopter EC 130 version B4 utrustad med HSI KI 525A
P/N 066-3046-07

ÅTGÄRD: Utför åtgärd enligt bifogad kopia av DGAC 2002-279-003(A)

TID FÖR ÅTGÄRD: Inom 100 flygtimmar eller 1 månad vilket inträffar först, räknat ifrån 8 juni 2002.

UNDERLAG: Eurocopter EC 130 Alert Telex No. 34A002

REFERENS: DGAC 2002-279-003(A)

BESLUTSDATUM: 3 juni 2002

LFS 2002:75

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2002-279-003(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

EC 130 helicopters

Navigation - Horizontal situation indicator KI 525A (ATA 34)

1. EFFECTIVITY

EC 130 version B4 helicopters equipped with HSI KI 525A.

2. REASON

This Airworthiness Directive is issued following the discovery of incorrect installation of HSI KI 525A P/N 066-3046-07 (non-compliance with equipment manufacturer ALLIEDSIGNAL Service Bulletin No. 341), which might result in navigation errors.

3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following measures are rendered mandatory from the effective date of this Airworthiness Directive.

- No later than within the next 100 flight hours or within 1 month (whichever limit is reached first):
 - a) Check the part number of HSI KI 525A installed on aircraft.
 - b) If the part number read is 066-3046-07, comply with the instructions given in paragraph 2.A.1 or paragraph 2.A.2 of referenced EUROCOPTER EC 130 Alert Telex No. 34A002 according to aircraft installation.

REF.: EUROCOPTER EC 130 Alert Telex No. 34A002.

EFFECTIVE DATE : JUNE 08, 2002

d/DJ

May 29, 2002

EUROCOPTER
EC 130 helicopters

2002-279-003(A)