
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av styrspak.

GÄLLER: Britten-Norman Islander och Trislander serien.

ÅTGÄRD: Utför åtgärd enligt bifogad kopia av CAA AD 004-05-2002

TID FÖR ÅTGÄRD: Inom 10 flygtimmar räknat från detta LVD's beslutsdatum.

UNDERLAG: Britten-Norman Service Bulletin SB 284.

REFERENS: CAA AD 004-05-2002

BESLUTSDATUM: 20 juni 2002

LFS 2002:92

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

Safety Regulation Group
Applications and Certification Section



**CIRCULATED TO ALL RESPONSIBLE
AUTHORITIES OF ICAO CONTRACTING STATES**

30 May 2002

Our Ref 9/97/CtAw/168/169

**NOTIFICATION TO FOREIGN AVIATION AUTHORITIES OF REQUIREMENTS MADE
MANDATORY BY THE UK CIVIL AVIATION AUTHORITY**

Please be advised that the Civil Aviation Authority has classified compliance with the following action as mandatory for aircraft on the United Kingdom Civil Register.

CAA Airworthiness Directive 004-05-2002

Applicability Britten-Norman Islander and Trislander Series aircraft.

Subject - Description Flight Control - Control column universal joint – Supplies of undersized components.

Compliance - Requirement (Summary) Compliance is required with B-N Group Service Bulletin SB 284 within 10 flying hours of receipt of the bulletin. The Service Bulletin requires inspection of the control column universal joint for undersized components. This action is required because a limited number of dimensionally incorrect universal joints have been identified where the joint diameter is shouldered to a smaller diameter than specified.

A handwritten signature in black ink, appearing to be 'R J Tew'.

R J Tew
Airworthiness Directive Co-ordinator