


SWEDISH AIRWORTHINESS **DIRECTIVES (SAD)**



Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No:

1-091

AIRCRAFT TYPE:

SAAB 2000

SERIAL No:s

AFFECTED:

SAAB 2000 -003 through -039

SUBJECT:

Oxygen System - Passenger Oxygen - Drop Out Boxes Inspection

BACKGROUND:

The Passenger Oxygen System failed to operate correctly in an aircraft after activation at a low cabin pressure. The following

failures were recognized. Some lids did not open

Some mask hoses disconnected from the generator outlet

connection

Some masks did not fall out

During a following inspection including other aircraft it was found

that:

- Two oxygen generators fell out with the mask on one aircraft

REFERENCE **DOCUMENTS:**

Saab Aircraft AB Service Bulletin SAAB 2000-35-001

ACTIONS:

Perform actions described in Saab Aircraft AB Service Bulletin SAAB 2000-35-001 dated 20 February, 1996, or later revision

COMPLIANCE

TIME:

To be performed within 30 calendar days after effective date of this

SAD

EFFECTIVE

DATE:

20 February, 1996

LUFTFARTSVERKET Flight Safety Department

LFS: 1996:18

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.

S-601 79 NORRKÖPING SWEDEN

Office address

Telephone No Nat 011 - 19 20 00 Cable address Civilair

Telex address

Vikboplan 11 Int +46 11 - 19 20 00 Norrköping

64250