

**SAD** No 1-009

## SWEDISH AIRWORTHINESS DIRECTIVES

## Section 1. Swedish manufactured **Aeronautical Products**

1-009 AIRWORTHINESS DIRECTIVE No

AIRCRAFT TYPE: SAAB-FAIRCHILD 340A

SERIAL No: AFFECTED: 340A-004 thru 048

SUBJECT: ENGINE CONTROLS - REPLACEMENT OF O-RING SEAL FITTING AND SEALING OF ENGINE CONTROL CABLES AT WING TO FUSELAGE INTERFACE

> Service experience has shown the possibility of incorrect fitness of O-ring seal fitting installed according to Service Bulletin SF 340-76-006 that may result in improper function of sealing ability. It is also necessary to introduce improved protection of the sleeves covering the control cables in the pressurized area.

REFERENCE DOCUMENT(S):

SAAB-SCANIA AB Service Bulletin

SF 340-76-007 Revision 3, August 14,

1985

COMPLIANCE TIME: Replacement as soon as possible but not

later than October 31, 1985

This Airworthiness Directive supersedes SAD No 1-004 Rev A Subject (A). Other parts of SAD

remain valid.

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.

1985-08-15 Norrköping

**Board of Civil Aviation** Flight Safety Department

1985:22

LFS

Uppvisad .....

Mail address

Office address

Telephone No

Directly

Mr Norén 19 20 62 Civilair

Cable address Telex address

→ S-601 79 NORRKÖPING