

Section 1. Swedish Manufactured Aeronautical Products

**AIRWORTHINESS**

**DIRECTIVE No:** 1-103R1

**AIRCRAFT TYPE:** SAAB 340B

**SERIAL No:s**

**AFFECTED:** SAAB 340B -342, -359 through -394, -396 through -404 and -406.  
*Note: Effectivity changed*

**SUBJECT:** Lights - Ceiling and Lavatory Lights - Inspection, Rework and Replacement of the Fluorescent Lamp Holders.

**BACKGROUND:** A number of failures have occurred in aircraft equipped with Page Aerospace Ltd., lampholders, where loose back covers have led to arcing between the fluorescent tube pins and the lampholders. Arcing may cause smoke in the compartment.

**REFERENCE  
DOCUMENTS:**

Saab Aircraft AB Service Bulletin SAAB 340-33-040 Rev 1, dated 29 January, 1997.

**ACTIONS:**

Perform actions described in Saab Aircraft AB Service Bulletin SAAB 340-33-040 Rev 1, dated 29 January, 1997, or later revision.

**COMPLIANCE**

**TIME:** To be performed not later than 1 March, 1997.  
*Note: Compliance time changed*

**EFFECTIVE**

**DATE:** 1997-01-30

**LUFTFARTSVERKET  
Flight Safety Department**

**LFS: 1997:8**

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.