

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-106R1

AIRCRAFT TYPE: SAAB SF340A and SAAB 340B

SERIAL No:s SAAB SF340A -121, -125 through -159
AFFECTED: SAAB 340B -160 through -360
All aircraft with a fire extinguisher installed in the forward Lavatory
Pt. No.55-373 (with external service).

SUBJECT: Equipment/Furnishing - Waste Bin Fire Extinguisher Located in the Forward
Lavatory - Inspection and Changed Procedure to Remove and Install it

BACKGROUND: On periodic checks of the forward lavatory waste bin fire - extinguisher the
capillary tube has been fractured/bent in the yellow area during
maintenance. This has caused the capillary tube to leak at the head and
discharge the contents of the fire extinguisher.

REFERENCE Saab Aircraft AB Service Bulletin SAAB 340-25-235
DOCUMENTS:

ACTIONS: Perform actions described in Saab Aircraft AB Service Bulletin SAAB
340-25-235 dated 11 December, 1996 or later revision.

COMPLIANCE To be performed within 3 months after effective date of this SAD
TIME:

EFFECTIVE 12 December, 1996
DATE: (Issued 8 September, 1998 to clarify original SAD 1-106)

LUFTFARTSVERKET
Aviation Safety Department

LFS 1998:57

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

| Mail address | Office address | Telephone No | Cable address | Telex address |
|----------------------|----------------|---------------------|---------------|---------------|
| SE-601 79 NORRKÖPING | Vikboplan 11 | Nat 011 19 20 00 | Civilair | 64250 |
| SWEDEN | | Int +46 11-19 20 00 | Norrköping | |
| | | Fax +46 11 19 25 15 | | |
| | | +46 11 19 25 75 | | |