

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-109

AIRCRAFT TYPE: SAAB 2000

SERIAL No:s

AFFECTED: SAAB 2000 -004 through -049

SUBJECT: Communications - Radio Tuning Unit - Installation of New Improved Radio Tuning Units

BACKGROUND: The manufacturer of the Radio Tuning Units have experienced a problem resulting in the possibility for both left and right side radios to change tuned frequencies and ATC codes following a single RTU black screen or "blinking" type of failure. In order to avoid the possibility of this problem, a new RTU is available. Installation of new RTU's also cancel the Alert Operations Bulletin No.8.

REFERENCE

DOCUMENTS: Saab AB Service Bulletin SAAB 2000-23-017 dated 10 March 1997.

ACTIONS: Perform actions described in Saab AB Service Bulletin SAAB 2000-23-017 dated 10 March, 1997 or later revision.

COMPLIANCE

TIME: To be performed not later than 01 April, 1998.

EFFECTIVE

DATE: March 12, 1997

LUFTFARTSVERKET
Aviation Safety Department

LFS 1997:15

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.