

(Cont)  
1685Date: 1980-12-01Time of compliance: Within 50 flight hours from the effective date of this Airworthiness Directive, or latest May 1, 1981, whichever occurs first.

1832

Subject: Inspection of elevator sparApplies to: SAAB-SAFIR 91B, 91B2, 91C, and 91DReason: Damage to elevator spar at bearing assembly attachment has been reported in a few casesRequired action: Carry out the required action in accordance with SAAB-SCANIA Service Bulletin No 91.1.004, Issue 2Date: 1982-09-27Time of compliance: Before further flight, if not already performed. Thereafter at intervals not exceeding 200 flight hours.