


LUFTFARTSVERKET
601 79 NORRKÖPING, SVERIGE
TEL: 011 - 19 20 00
TELEGRAMADRESSER:
LUFTFARTSNÄTET ESKLYA
KOMM CIVILAIR NORRKÖPING
TELEX 64250

AIRWORTHINESS DIRECTIVES

LUFTVÄRDIGHETS- ANVISNINGAR (LVA)

Aircraft
SAAB-MFI 15 - 2



AD Nos.

1794

Subject: Repair of cracks in metal parts, wing carry through

Applies to: SAAB-MFI 15-200 and SAAB-MFI 15-200A, all serial numbers

Reason: Cracks have been found in some cases in sheet metal part 5800127-001/-002

Required action: Check for cracks in the area where wing carry through is attached and perform if necessary, suggested repair in accordance with SAAB-SCANIA Service Bulletin SB 15.024

Date: 1982-03-22

Time of compliance: Within 100 flight hours from the effective date of this Airworthiness Directive unless already accomplished

1982-03-22

Åtgärd enligt LVA utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Anteckning om åtgärd, som vidtagits i enlighet med LVA, skall införas i resedagbok och/eller journal för berörd flygmateriel med hänvisning till ifrågavarande LVA-nummer.