

Sektion 2. Utlandstillverkad flygmateriel

TITEL: Korrosionskontroll av höjdroderets torsionsrör

GÄLLER: B121 Pup 1,2 och 3.

ÅTGÄRD: Kontrollera höjdroderets torsionsrör för korrosion och åtgärda i enlighet med British Aerospace Alert Service Bulletin B121/28 revision 1 eller senare utgåva.

TID FÖR ÅTGÄRD: I tid och intervaller enligt para (1), (2) och (3) i bifogad kopia av CAA AD 001-11-91.

UNDERLAG: British Aerospace Alert Service Bulletin nr B121/28 revision 1 eller senare utgåva.

REFERENS: CAA AD 001-11-91

UTGIVNINGS-DATUM: 1992-01-30

LFS: 1992:2

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

.....

CAA AIRWORTHINESS DIRECTIVE 001-11-91

APPLICABILITY British Aerospace Beagle B121 Pup Series 1, 2 and 3 aircraft.

SUBJECT - DESCRIPTION Flight Controls - Corrosion of elevator torque tubes.

COMPLIANCE - REQUIREMENT (SUMMARY) Compliance is required with British Aerospace Alert Service Bulletin No. B121/28 Revision No. 1 at the following thresholds.

- (1) Where there is no record of previous compliance in the 36 months before the date of receipt comply with Part 1 of the bulletin within 10 flying hours.
- (2) Where there is a record of previous compliance in the 36 months before the date of receipt comply with Part 1 of the bulletin within 36 months from that compliance date.
- (3) Comply with Part 2 of the bulletin within 36 months of the date of accomplishment of Part 1 and thereafter at intervals not exceeding 36 months.

The Alert Service Bulletin is in two parts Part 1 introduces a once only inspection of the elevator torque tubes for corrosion and Part 2 introduces repeat inspections in the same area. This action is required because a severely corroded torque tube assembly has been found on an aircraft during a major inspection.