

Sektion 2. Utlandstillverkad flygmateriel

R1

SUBJECT: Overhead Stowage Bins B737

AIRCRAFT TYPE
AND SERIAL NO:s

AFFECTED: Applies to Boeing Model 737 series airplanes listed into the following Boeing Service Bulletins:

- 737-25A-1283, revision 1 dated March 19, 1992
- 737-25-1291 dated December 18, 1991
- 737-25-1294 dated February 20, 1992

ACTIONS: To ensure the structural integrity of the overhead stowage bins perform actions as applicable in Service Bulletins above.

COMPLIANCE
TIME:

- A. Not later than 1 May 1993 all affected airplanes have to be modified in accordance with above mentioned Service Bulletins.
- B. An alternative method of compliance or adjustment of the compliance time, which provides an acceptable level of safety may be used when approved by LFV.

REFERENCE
DOCUMENTS:

Boeing Service Bulletins:
737-25A-1283, revision 1 dated March 19, 1992
737-25-1291 dated December 18, 1991
737-25-1294 dated February 20, 1992

JAA/CERT/AD/B737/757/92-L153 (Agreed JAA policy)

EFFECTIVE
DATE: 1992-12-03

LFS: 1992:38

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.