

SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

SAD No 1-118 R1

Cancels SAD No 11118

Aviation Safety Department

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO:

1-118R1

AIRCRAFT TYPE: SAAB 340B

SERIAL No:s

SAAB 340B-162, 163, 171, -205, -207, -230, -276, -281, -289, -292, -296, -

AFFECTED:

302, -308, -310, -311, -315, -316, -318, -327, -328, -331, -333, -336, -337, -

351, -355, -357, -360 through -365, -368, -378, -399.

Note: Aircraft effectivity increased

SUBJECT:

Equipment/Furnishings - Cargo Bay Placards - Installation of Baggage Net

Placards to the Aft Face of the Kinked Bulkhead and the RH Cargo Bay

Panel.

BACKGROUND:

It has been found that where the baggage net Pt. No. 7225572-551 has

been installed in combination with the kinked bulkhead, the forward webbing of the net is too close to the aft face of the bulkhead such that baggage may

overload the bulkhead's floor attachments outside the existing limits.

REFERENCE

Saab Aircraft AB Mandatory Service Bulletin SAAB340-25-244 revision 1

DOCUMENTS:

dated 5 May, 2000.

ACTIONS:

Perform actions described in Saab Aircraft AB Mandatory Service Bulletin

SAAB340-25-244 revision 1 dated 5 May 2000, or later revision.

COMPLIANCE

TIME:

To be performed within 3 months after effective date of this SAD.

EFFECTIVE

DATE:

5 May, 2000

LUFTFARTSVERKET **Aviation Safety Department**

LFS 2000:67

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Fax

Mail address

Office address

Telephone No

Cable address Civilair

Telex address 64250

SE-601 79 NORRKÖPING **SWEDEN**

Vikboplan 11

Nat 011 19 20 00 +46 11-19 20 00 Int

+46 11 19 25 15 +46 11 19 25 75 Norrköping