
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-178

AIRCRAFT TYPE: SAAB 2000

SERIAL No:s

AFFECTED: SAAB 2000 - 004 thru - 039

SUBJECT: Windows - Inspection of Windshield Wiper Spoiler

BACKGROUND: Recent findings on aircraft in service have revealed that aircraft covered by the effectivity of Service Bulletin Saab 2000-56-002 have been found with cracked or completely lost spoilers on several occasions. This is due to the fact that Service Bulletin 2000-56-002 has not been implemented. Parts that come off the aircraft in this area can cause damage to the propellers, engine and structure. Referenced Service Bulletin requires inspection of the integrity of the windshield wiper spoiler installation and subsequent modification.

REFERENCE DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 2000-56-003 dated 12 August, 2002.

ACTIONS: Perform actions described in Saab Aircraft AB Service Bulletin SAAB 2000-56-003 dated 12 August, 2002 or later revision.

COMPLIANCE TIME: To be performed within 400 flights from the release date of this SAD and then repetitively every 400 flights until the corrective action is performed.

EFFECTIVE DATE: 15 August 2002

LFS: 2002:109

LUFTFARTSVERKET
Aviation Safety Authority

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address	Office address	Telephone number	Fax number	Cable address	Telex address
SE-601 79 NORRKÖPING	Vikboplan 11	+46 11 19 20 00	+46 11 19 25 15	Civilair	64250
SWEDEN	Norrköping		+46 11 19 25 75	Norrköping	