

Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av dräneringshål i bränsletankarnas inre sryglar

GÄLLER: TB9, TB10, TB20, TB21, TB200 med S/N angivna i bifogad kopia av DGAC AD 94-247(A)

ÅTGÄRD: Utför åtgärder angivna i SOCATA TB SB nr 10.084.57

TID FÖR
ÅTGÄRD: Inom 100 flygtimmar men senast den 31 oktober 1995.

UNDERLAG: SOCATA TB SB 10.084.57

REFERENS: DGAC AD 94-247(A) (kopia bifogad).

UTGIVNINGS-
DATUM: 1994-12-22

LFS: 1994:46

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarende flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this

Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

ref.: 94-247 (A)

In case of any difficulty, reference should
be made to the French original issue.

SOCATA

TB9, TB10, TB20, TB21, TB200 Airplanes

Wing ribs, fuel tank area

This Airworthiness Directive concerns TB airplanes S/N 1038 to 1442, 1444 to 1462, 1464 to 1581, 1583 to 1606, 1608 to 1619, 1629, and airplanes S/N 1 to 1037 on which the tank rib has been repaired since the application of the modification N° 78.

In order to avoid clogging of drain holes with PR sealant on fuel tank internal ribs, the following measures are made mandatory from the effective date of this Airworthiness Directive :

- Within next 100 hours T.I.S. and at the latest on October 31, 1995, perform the inspections described in SOCATA TB SB 10.084.57.

Record the application of this Airworthiness Directive on the aircraft Log book.

Ref : SOCATA TB Airplane SB 10.084.57

EFFECTIVE DATE : DECEMBER 03, 1994

v/JB

November 23, 1994

SOCATA
TB9, TB10, TB20, TB21, TB200 Airplanes

94-247 (A)