
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-193

AIRCRAFT TYPE: SAAB SF340A and 340B

SERIAL No:s

AFFECTED: SAAB SF340A-004 through -159

SAAB 340B-160 through -459

SUBJECT: ICE & RAIN PROTECTION - WINDSHIELD WIPERS - INSPECTION OF THE WIPER ARM ASSEMBLY

BACKGROUND: A Swedish Airworthiness Directive 1-115 was issued after incidents where windscreen wiper blade separated from the wiper arm causing propeller damage and penetration of the left fuselage skin. Due to additional occurrence it has been necessary to perform an extended inspection.

REFERENCE DOCUMENTS: Saab AB Service Bulletin SAAB 340-30-088 dated 07 October 2003 or later revision

ACTIONS: Perform actions described in Saab AB Service Bulletin SAAB 340-30-088.

COMPLIANCE TIME: To be performed within 6 months after effective date of this SAD.

EFFECTIVE DATE: 8 October 2003

LFS 2003:119

LUFTFARTSVERKET
Aviation Safety Authority

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address
SE-601 79 NORRKÖPING
SWEDEN

Office address
Vikboplan 7
Norrköping

Telephone number
+46 11 19 20 00

Fax number
+46 11 19 25 15
+46 11 19 25 75

Cable address
Civilair
Norrköping

Telex address
64250