
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av ventil i oljesystemet

GÄLLER: Zlin 242L S/N upp t o m 0708 samt 0727 och 0728 med installerad ventil enligt Drwg No L 242L.7100-04.00

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av Czech Republic CAA-AD-2-029/97

TID FÖR ÅTGÄRD: Före flygning räknat från detta LVD's utgivningsdatum

UNDERLAG: CAA-AD-2-029/97
Mandatory Service Bulletin No Z 242L/25a

REFERENS: Czech Republic CAA-AD-2-029/97

BESLUTSDATUM: 1997-06-06

LFS 1997:26

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450



CIVIL AVIATION AUTHORITY
CZECH REPUBLIC

airport Ruzyně, 160 08 Prague 6
tel: 420 02/324086, fax: 420 02/364112

AIRWORTHINESS DIRECTIVE

Number: CAA - AD - 2 - 029/97

Date of issue: May 29, 1997

MORAVAN Inc.
ZLIN 242L

AIRCRAFT - the sludge valve of the oil system - check for proper locking

Applicable:

All Zlin 242L aircraft up to S/N 0708 and S/N 0727 and 0728 with the sludge valve of the oil system Drwg. No. L 242L.7100-04.00 installed.

Reason for issuance:

Manufacturer found out that the sludge valve of the oil system Drwg. No. L 242L.7100-04.00 installed on the forementioned aircraft may cause the oil leakage from the engine.

Effective date: June 5, 1997

Apply until:

Prior next flight after effective date of this AD.

Accomplishment Procedure:

Perform proper locking of the nut in assembly of the lifter and the valve sealing disc in accordance with Mandatory Service Bulletin No. Z 242L/25a.

Remarks:

- Where applicable, the requirements of this AD must be integrated into the aircraft log book
- Address inquiries this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyně Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 324086, fax: 420 2 364112
- Operators of affected aircraft obtain copies of mandatory service bulletin No. Z 242L/25a directly from manufacturer. Contact address: MORAVAN, Inc., 765 81 Otrokovice, CZECH REPUBLIC

Ing. Pavel MATOUŠEK
Director of Airworthiness Division
Civil Aviation Authority