



LUFTFARTSVERKET

Luftfartsinspektionen

LUFTVÄRDIGHETSDIREKTIV

(LVD)

A. Flygplan
Extra
LVD Nr 2789R1
Upphäver LVD 2789

Sektion 2. Utlandstillverkad flygmateriel

TITEL: Installation av skydd för främre sätets säkerhetsbälte

GÄLLER: Extra EA 300/200, S/N 1 t o m 15

ATGÄRD: Utför åtgärder angivna i Extra EA-300 Service Bulletin No. 300-1-97 Issue B daterad 11 juni 1997.

TID FÖR ATGÄRD: Före flygning

UNDERLAG: Extra EA-300 Service Bulletin No. 300-1-97 Issue B daterad 11 juni 1997 eller senare utgåva.

REFERENS: LBA AD 97-203/2 (kopia bifogas).

BESLUTSDATUM: 1998-03-02

LFS 1998:11

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450



**Airworthiness
Directive
1997-203/2**

Luftfahrt-Bundesamt
Airworthiness Directive Section
Lilienthalplatz 6
38108 Braunschweig
Federal Republic of Germany

Extra Flugzeugbau

Effective Date: February 26, 1998

Affected:

Kind of aeronautical product:	Aircraft
Manufacturer:	Extra, Hünxe, Germany
Type:	Extra EA 300
Models affected:	Extra EA 300/200
Serial numbers affected:	01 up to and including 15
German Type Certificate No.:	1086

Bilaga till LVD 2789R1

Subject:

Front seat belt safety cover installation.

Reason:

A rudder pedal lock due to interference with the front seat belt harness has been reported.

Action:

Install a front seat belt cover.

Note:

If the belt cover was installed in accordance with AD-No. 97-203, check the installation procedure in accordance with Issue B of the Service Bulletin and if all in the new SB listed parts („List of used Parts“) were installed.

Compliance:

Action must be performed before the next flight.

Technical publication of the manufacturer:

Extra EA-300 Service Bulletin No. 300-1-97 Issue B dated June 11, 1997 which becomes herewith part of this AD and must be obtained from Messrs.:

Extra Flugzeugbau
Flugplatz Dinslaken

D-46569 Hünxe
Federal Republik of Germany
Fax: + 49 (0) 2858 913730

Accomplishment and log book entry:

Action to be accomplished by an approved service station and to be checked and entered in the log book by a licensed inspector.

Note:

This AD supersedes AD-Nr.: 97-203 dated July 03, 1997.