
Section 1. Swedish Manufactured Aeronautical Products

Airworthiness Directive No.: 1-034

Aircraft Type: SF340A (SAAB-FAIRCHILD 340A) and SAAB 340B

Serial Nos. Affected: SF340A-004 through -159 and SAAB 340B-160 through -166

Subject: Nacelle - Inspection of drag strut bolts, lower fittings and attaching fasteners

Background: A few cases of loose nuts at the lower drag strut support fittings in the nacelles have been reported, which could result in loose fittings. This condition, if not corrected, could in the case of a double failure, result in loss of structural integrity of the powerplant installation.

Reference documents: SAAB-SCANIA AB Service Bulletin No. SAAB 340-54-026

Actions: Perform inspection and correction in accordance with SAAB-SCANIA AB Service Bulletin No. SAAB 340-54-026, dated December 1, 1989, or later revision

Compliance Time: Task 1. To be performed within 200 FH after effective date of this SAD
Task 2. To be performed at next engine removal or 1500 FH after effective date of this SAD

Norrköping 1989-12-08

LUFTFARTSVERKET
Flight Safety Department

LFS: 1989:24

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.