

---

Sektion 2. Utlandstillverkad flygmateriel

---

**TITEL:** Kontroll av säkringar

**GÄLLER:** SA 360 C och 365 versionerna C, C1, C2, C3 med säkrings P/N angivna i bifogad kopia av DGAC AD 98-112-042(A)

**ÅTGÄRD:** Utför åtgärder angivna i DGAC AD 98-112-042(A)

**TID FÖR ÅTGÄRD:** Inom tider angivna i DGAC AD 98-112-042(A) punkt 1 och 2 räknat från detta LVD's beslutsdatum

**UNDERLAG:** DGAC AD 98-112-042(A)  
Eurocopter SA 360/365 Service Bulletin No.01.36

**REFERENS:** DGAC AD 98-112-042(A)

**BESLUTSDATUM:** 1998-04-07

**LFS 1998:21**

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

|                   |              |               |                        |       |
|-------------------|--------------|---------------|------------------------|-------|
| Postadress        | Gatuadress   | Telefonnummer | Telegram               | Telex |
| 601 79 NORRKÖPING | Vikboplan 11 | 011-192000    | Civilair<br>Norrköping | 62450 |

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this*

*Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

ref.: 98-112-042(A)

In case of any difficulty, reference should  
be made to the French original issue.

## EUROCOPTER

### SA 360 C and SA 365 C Helicopters

#### Single-Pole Circuit Breakers

This Airworthiness Directive applies to SA 360 C helicopters and SA 365 helicopter versions C, C1, C2, C3 fitted with CROUZET single-pole circuit breakers bearing the following part numbers :

- |                            |                            |
|----------------------------|----------------------------|
| - 1 ampere : 84 400 028    | - 7,5 amperes : 84 400 033 |
| - 2 amperes : 84 400 029   | - 10 amperes : 84 400 034  |
| - 2,5 amperes : 84 400 030 | - 15 amperes : 84 400 035  |
| - 3 amperes : 84 400 031   | - 20 amperes : 84 400 036  |
| - 5 amperes : 84 400 032   | - 25 amperes : 84 400 037  |

In order to ensure that the single-pole circuit breakers listed above are not affected by loss of electrical continuity, the following measures are rendered mandatory from the effective date of this Airworthiness Directive :

1. Within 100 flying hours, without exceeding 3 months (the first limit reached is to be taken into account), check in accordance with the instructions given in paragraph 2B of EUROCOPTER SA 360/365 Service Bulletin No. 01.36 referenced below, all circuit breakers bearing part numbers 84 400 ---, which are fitted to the systems listed in paragraph 1D1 of the same Service Bulletin.
2. Within 500 flying hours, without exceeding 6 months (the first limit reached is to be taken into account), apply the instructions given in paragraph 2B of the referenced Service Bulletin to all the circuit breakers of the remaining systems.

.../...

n/DJ

March 11, 1998

EUROCOPTER  
SA 360 C and SA 365 C Helicopters

98-112-042(A)

3. The use of circuit breakers covered by this Airworthiness Directive is prohibited from December 31, 1999.
4. Before installing a circuit breaker, held as spares, and covered by this Airworthiness Directive, on an aircraft, torque tighten and check the circuit breaker in accordance with the instructions given in paragraph 2B (1) and 2B (2) of the referenced Service Bulletin.

---

Ref. : EUROCOPTER SA 360/365 Service Bulletin No. 01.36

---

EFFECTIVE DATE : MARCH 21, 1998