
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Kontroll av ytbehandling av nosställets cylindrar

GÄLLER: BN2, BN2A, BN2B, BN2T och BN2A-Mk III Trislander

ÅTGÄRD: Utför åtgärder angivna i bifogad kopia av CAA AD 004-12-98

TID FÖR ÅTGÄRD: I enlighet med Britten-Norman Service Bulletin BN2/SB 249

UNDERLAG: CAA AD 004-12-98
Britten-Norman Service Bulletin BN2/SB 249

REFERENS: CAA AD 004-12-98

BESLUTSDATUM: 1999-03-26

LFS 1999:61

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.

Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Telegram	Telex
601 79 NORRKÖPING	Vikboplan 11	011-192000	Civilair Norrköping	62450

Bilaga till LVD 2963

CAA AIRWORTHINESS DIRECTIVE 004-12-98

APPLICABILITY Britten-Norman BN2, BN2A, BN2B and BN2T Islander aircraft and BN2A-Mk III Trislander aircraft.

SUBJECT - DESCRIPTION Landing Gear - Nose landing gear assembly 3501H2 and 3811H2, chrome plating - Examine

COMPLIANCE - REQUIREMENT (SUMMARY) Compliance is required with Britten-Norman Service Bulletin BN2/SB.249 before further flight if stiffness or restriction is found in the function of the rudder and nose wheel steering system or at the next 100 hour inspection. The Service Bulletin requires compliance with Fairey Hydraulics Service Bulletin 32-19 which requires a check for integrity of chrome plating embodied by repair to external upper and lower bearing surfaces of the nose landing gear cylinder assembly. This action is required because there has been an occurrence where the chrome plating added by the embodiment of a Fairey Hydraulics repair scheme to either or both of the upper and lower bearing surfaces of the cylinder assembly has delaminated causing stiffness in the operation of the rudder and nose wheel steering.