
Sektion 2. Utlandstillverkad flygmateriel

TITEL: **Ändring av flygtidsbegränsning**

GÄLLER: Z-142C och Z-242L med S/N angivna i bifogade kopior av
CAA AD: T-099/2000R1, T-100/2000, T-101/2000.

ÅTGÄRD: Utför åtgärder angivna i ovan nämnda AD:s.

TID FÖR ÅTGÄRD: Inom tider angivna i ovan nämnda AD:s.

UNDERLAG: Tillämpliga Mandatory Service Bulletines angivna i
ovannämnda angivna AD:s

REFERENS: CAA-AD-T-099/2000R1, T-100/2000, T-101/2000

BESLUTSDATUM: 6 juli 2001

LFS 2001:93

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

(1)

LUFTFARTS-
INSPEKTIONEN

2001-07-02

CAA

CIVIL AVIATION AUTHORITY
CZECH REPUBLICAirport Ruzyne, 160 08 Prague 6
tel: 420-2-33320922, fax: 420-2-20562270AIRWORTHINESS
DIRECTIVE

Number: CAA-AD-T-099/2000R1

Supersedes CAA-AD-T-088/1999,
CAA-AD-T-091/1999, CAA-AD-T-
125/1999, CAA-AD-T-126/1999, CAA-
AD-T-099/2000

Date of issue: June 28, 2001

MORAVAN-AEROPLANES Inc.
Z-142C, Z-242L

AIRCRAFT - LIMITATION OF OPERATION

Applicability: Applicable to Moravan-Aeroplanes Inc. made aircraft mentioned bellow:

Z-142C S/N up to 0560 incl.

Z-242L S/N up to 0656 incl. in case when the Mandatory Service Bulletin Z 242L/27a-Rev. 1 was not performed.

Reason: It was detected that the airplanes used in the aerobatic category in accordance with the Airplane Flight Manual limitations may be operated over the CAA-FAA spectrum of loads limits on which the technical service life of the airframe was based.


New limitation of operation in Aerobatic and Utility category was determined on the base of flight tests:

The operation is limited to 190 flight hours flying in either "AEROBATIC or UTILITY" category with the total service flight time remaining on 3500 flight hours.

Effective date: Upon receipt.**Compliance :**

Action must be done prior to further flight in accordance with Mandatory Service Bulletin No. Z 142C/17a, Z 242L/37a-Rev. 1, which becomes herewith part of this AD and may be obtained from: MORAVAN-AEROPLANES Inc. Otrokovice, Obchodně technické služby, 765 81 Otrokovice, CZECH REPUBLIC, phone: +420/67/767 1111, fax.: +420/67/7922103.

Remarks: - The compliance of this AD must be recorded in Aircraft Logbook, where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation
- Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 2 33320922, fax: 420 2 20562270.
- This AD supersedes CAA-AD-T-088/1999, CAA-AD-T-091/1999, CAA-AD-T-125/1999, CAA-AD-T-126/1999, CAA-AD-T-099/2000.

for Ing. Pavel MATOUŠEK
Director of Airworthiness Division
CAA CZ