
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-087

AIRCRAFT TYPE: SAAB 2000

SERIAL No:s

AFFECTED: SAAB 2000 -003 through -014

SUBJECT: Equipment / Furnishing - Replacement of Thermal Insulation

BACKGROUND: It has been found that the insulation pads between STA 1005.5 and STA 1027.5 are made of pads bonded together to make the correct thickness.

As a result of that, these pads do not meet the applicable fire protection requirements.

REFERENCE

DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 2000-25-016 dated 30 January, 1996.

ACTIONS: Perform actions described in Saab Aircraft AB Service Bulletin SAAB 2000-25-016 dated 30 January, 1996, or later revision.

COMPLIANCE

TIME: To be performed within 800 flight hours after effective date of this SAD.

EFFECTIVE

DATE: 30 January, 1996

LUFTFARTSVERKET
Flight Safety Department

LFS: 1996:11

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.