
Sektion 2. Utlandstillverkad flygmateriel

TITEL: Utbyte av tätning på "MGB mobile cowlings"

GÄLLER: Helikoptrar, Eurocopter AS 350 modell B, B!, B2, B3, BA, BB och D levererade före 2002-07-01

ÅTGÄRD: Utför åtgärder enligt bifogad DGAC AD 2002-537-094(A).

TID FÖR ÅTGÄRD: Före 2003-05-31

UNDERLAG: DGAC AD 2002-537-094(A). Eurocopter AS 350 Alert Service Bulletin No: 53.00.31.

REFERENS: DGAC AD 2002-537-094(A)

BESLUTSDATUM: 28 oktober 2002

LFS 2002: 141

Åtgärder enligt LVD utgör nödvändig förutsättning för ifrågavarande flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senast gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

Postadress	Gatuadress	Telefonnummer	Faxnummer	Telegram	Telex
601 79 NORRKÖPING	Vikobplan 11	011-19 20 00	011-19 25 75	Civilair Norrköping	62450

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2002-537-094(A)
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

AS 350 helicopters

MGB - Mobile cowling seals (ATA 53)

1. EFFECTIVITY

AS 350 helicopters versions B, B1, B2, B3, BA, BB and D, delivered before July 1st, 2002.

2. REASON

This Airworthiness Directive (AD) is issued following the discovery of the low fire-resistance of neoprene seals that are bonded to the MGB mobile cowlings. This resistance does not meet the certification criteria. In the event of an uncontrolled fire in the engine compartment, the fire could spread to the MGB compartment.

3. MANDATORY ACTIONS AND COMPLIANCE TIME

The following measures are rendered mandatory from the effective date of this AD:

- On May 31, 2003 at the latest, replace the former neoprene seals on the MGB mobile cowlings with new glass/silicone seals, in compliance with the instructions described in paragraph 2.B. of referenced EUROCOPTER AS 350 Alert Service Bulletin No. 53.00.31.

REF.: EUROCOPTER AS 350 Alert Service Bulletin No. 53.00.31.

EFFECTIVE DATE : NOVEMBER 09, 2002

n/DJ

October 30, 2002

EUROCOPTER
AS 350 helicopters

2002-537-094(A)