
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-139 R1

AIRCRAFT TYPE: SAAB SF340A and SAAB 340B

SERIAL No:s SAAB SF340A, S/N 004 through 159 and SAAB 340B S/N 160 through 459
AFFECTED: equipped with ABSC Brake Stack or Hitco Technologies, Inc. Brake Stack Kit, FAA STC No. ST00341LA

SUBJECT: Landing Gear- Brakes - Inspection of installation combination of the brake stack assemblies.

BACKGROUND: During introduction of ABSC brake assembly 5012589-3 (SB 340-32-113) a restriction regarding the installation combinations of brake assemblies (5012589-1, 5012589-2 and 5012589-3) was found necessary in order to avoid unbalanced aircraft handling situation and degradation of brake performance. Only symmetrical brake assemblies installations are permitted.

Hitco Technologies, Inc Brake Stack Kit part number 3001049, FAA STC No. ST00341LA applies only to ABSC brake assemblies 5012589-1 or 5012589-2.

REFERENCE SAAB Aircraft AB Service Bulletin SAB 340-32-114, dated 4 May 1998
DOCUMENTS: FAA STC No. ST00341LA.

ACTIONS: Perform actions described in SAAB Aircraft Bulletin SAAB 340-32-114, dated 4 May 1998 or later revision. All approved combinations are to be found in table 1 on page 2 in above SB.

COMPLIANCE To be performed within 2 months after effective date of this SAD.
TIME:

EFFECTIVE 1999-10-01
DATE:

LUFTFARTSVERKET
Aviation Safety Department

LFS 1999:148

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address
SE-601 79 NORRKÖPING
SWEDEN

Office address
Vikboplan 11
Norrköping

Telephone number
+46 11 19 20 00

Fax number
+46 11 19 25 15
+46 11 19 25 75

Cable address
Civilair
Norrköping

Telex address
64250