

Sektion 2. Utlandstillverkad flygmateriel

- TITEL:** "Swashplate bearing" för huvudrotorn.
- GÄLLER:** AS 350 alla S/N av modellerna B-B1-B2-D med lager P/N installerade enligt bifogad kopia av DGAC AD 89-155-054(B)R4.
- ÅTGÄRD:**
- 1.1 Kontrollera spel och kärvhet enligt instruktioner i paragraf 5.2.b av M.E.T arbetskort 62.30.00.601.
- 1.2 Kontrollera "swashplate" lagrets moment enligt instruktioner i paragraf 1C-c av AS 350 Service Bulletin No 62-12 rev. 2.
- 1.3 Kontrollera att "swashplate" lagret är rätt installerat enligt instruktioner i paragraf 1C-d av AS 350 Service Bulletin No. 62-12 rev. 2.
- 1.4 Kontrollera "swashplate" lagrets smörjning enligt instruktioner i paragraf 1C-e av AS 350 Service Bulletin No. 62-12 rev. 2.
- TID FÖR ÅTGÄRD:**
1. Inom 10 flygtimmar (om ej tidigare utfört) räknat från detta LVD:s utgivningsdatum.
2. Efter sista flygning för dagen, utför åtgärd enligt instruktioner i paragraf 1.C-g av AS 350 Service Bulletin No.62-12 rev. 2.
3. Repetera utförandet av paragraferna 1.2 och 1.3 av denna LVD varje gång vid byte av "swashplate" lager.
4. Repetera utförandet av paragraf 1.4 av denna LVD i intervaller av max 100 flygtimmar enligt instruktionerna i paragraf 1.C-i av AS 350 Service Bulletin No.62-12 rev. 2.
5. Inför Service Bulletin No. 62-02 senast vid nästa typ T inspektion.
- UNDERLAG:** Service Bulletin AS 350 No. 62-12 rev. 2 eller senare utgåva.
- REFERENS:** AD DGAC 89-155-054(B) R4
- UTGIVNINGSDATUM:** 1991-11-07

LFS: 1991:29

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarende flygmateriels luftvärdighet. Referens BCL M 1.11.
Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.:

89-155-054(B)R4
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE AS 350 helicopters

Swashplate

The present Airworthiness Directive applies to AEROSPATIALE AS 350 helicopters all serial numbers of versions B - B1 - B2 - D on which the swasplate is fitted with bearings P/N's :

- VH 36132 (704A33.651.051)
- Y 51BB 10843 S1 M 73 (704A33.651.080)
- INA 36132 A (704A33.651.126).

Subsequent to an accident caused by seizure of the swashplate bearing, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

- 1 - Within the next 10 flying hours (excepting when already carried out) :
 - 1.1. Check for play and hard points, as per instructions in paragraph 5.2.b of M.E.T. work card 62.30.00.601.
 - 1.2. Check swashplate bearing torque as per instructions in paragraph 1.C-c of referenced Service Bulletin.
 - 1.3. Check that the swashplate bearing is correctly installed, as per instructions in paragraph 1.C-d of referenced Service Bulletin.
 - 1.4. Check swashplate bearing lubrication, as per instructions in paragraph 1.C-e of referenced Service Bulletin.
- 2 - After the last flight of the day, comply with the instructions given in paragraph 1.C-g of referenced Service Bulletin.

.../...

e/W

October 2, 1991

AEROSPATIALE AS 350 helicopters

89-155-054(B)R4

- 3 Repeat the application of paragraphs 1.2 and 1.3 of this Airworthiness Directive each time the swashplate bearing is replaced.
- 4 Repeat the application of paragraph 1.4 of this Airworthiness Directive at intervals of no more than 100 hours, as per the instructions given in paragraph 1.C-i of referenced Service Bulletin.
- 5 Embody AS 350 Service Bulletin N° 62-02 during the next type T inspection at the latest.

Ref. : AS 350 Service Bulletin N° 62-12 rev. 2

The present revision 4 supersedes the AD
89-155-054(B)R3 dated May 2, 1991

EFFECTIVE DATES :

ORIGINAL AD AND REVISION 1 : OCTOBER 28, 1989
REVISION 2: JANUARY 6, 1990
REVISION 3 : MAY 12, 1991
REVISION 4 : OCTOBER 12, 1991