

Sektion 2. Utlandstillverkad flygmateriel

R1

TITEL: Byte av bränsletankarnas urluftningsslangar

GÄLLER: TB 20 och TB 21 S/N 1 t o m 1500 undantagna S/N 1456, 1463, 1473, 1490 och 1499.

ÅTGÄRD: Utför åtgärder i enlighet med SOCATA TB Service Bulletin Nr 10.067.28 Rev. 1.

TID FÖR ÅTGÄRD: Vid nästa 100 timmars tillsyn.

UNDERLAG: SOCATA TB Service Bulletin TB 10.067.28 R1(KIT OPT 10.9187/88-57)

REFERENS: DGAC AD 92-225(A). R1.

UTGIVNINGS-DATUM: 1993-05-06

LFS:1993:17

Åtgärd enligt LVD utgör nödvändig förutsättning för ifrågavarende flygmateriels luftvärdighet. Referens BCL M 1.11. Anteckning om åtgärd, som vidtagits i enlighet med LVD, skall införas i teknisk journal för berörd flygmateriel med hänvisning till ifrågavarande LVD-nummer. Angivet underlag refererar till senaste gällande revision/utgåva. LVD utges i luftfartsverkets författningssamlingar LFS.

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 92-225(A)R1

In case of any difficulty, reference should be made to the French original issue.

SOCATA

TB 20 - TB 21 Airplanes

Fuel tank air vent system

This Airworthiness Directive concerns TB 20 and TB 21 airplanes from S/N 1 to S/N 1500 inclusive, except S/N 1456, 1463, 1473, 1490 and 1499.

In order to avoid a risk of air vent hoses disconnection due to vinyl hardening/ageing, the following measures are made mandatory from the effective date of this Airworthiness Directive.

- Within the next 100 hours time-in-service, replace all air vent hoses in compliance with instructions provided in SOCATA TB Airplanes Service Bulletin No 10.067.28 R1 (KIT OPT 10.9187-57 or OPT 10.9188-57).

Record the application of present Airworthiness Directive in airplane log book.

Ref : SOCATA TB Airplanes Service Bulletin TB 10.067.28 Rev. 1

The present Revision 1 replaces original AD 92-225(A) dated October 28, 1992

EFFECTIVE DATES :

Original AD : UPON RECEIPT
Revision 1 : APRIL 24, 1993

April 14, 1993

SOCATA
TB 20 - TB 21 Airplanes

92-225(A)R1

n/Z
17