



LUFTFARTSVERKET

Aviation Safety Department

**SWEDISH AIRWORTHINESS
DIRECTIVES (SAD)**

SAD No 1-119R1

Cancels SAD No 1-119

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-119R1

AIRCRAFT TYPE: SAAB SF340A and SAAB 340B

SERIAL No:s SAAB SF340A-004 through -159 and
AFFECTED: SAAB 340B-160 through -219 and -402 through -436 equipped with
Aerospace Composite Technologies (ACT) Engine Air Intakes.
Note: Effectivity changed

SUBJECT: Ice & Rain Protection - Engine Air Intake -Modification of the Detachable
Center Inlet.

BACKGROUND: The design and manufacturing method of the detachable center inlet
produces two apertures at the rear of the component. These holes must be
closed to fully comply with fire resistance regulations.

REFERENCE Saab AB Service Bulletin SAAB 340-30-073 Revision 1 dated October 1,
DOCUMENTS: 1998 and Attachment 1.

ACTIONS: Perform actions described in Saab AB Service Bulletin SAAB 340-30-073
Revision 1, dated October 1, 1998, and Attachment 1, or later revision.

COMPLIANCE To be performed within two years from the effective date of this SAD.
TIME:

EFFECTIVE 8 October, 1998
DATE:

LUFTFARTSVERKET
Aviation Safety Department

LFS 1998:66

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

| | | | | |
|----------------------|----------------|---------------------|---------------|---------------|
| Mail address | Office address | Telephone No | Cable address | Telex address |
| | | Nat 011 19 20 00 | Civilair | 64250 |
| SE-601 79 NORRKÖPING | Vikboplan 11 | Int +46 11-19 20 00 | Norrköping | |
| SWEDEN | | Fax +46 11 19 25 15 | | |
| | | +46 11 19 25 75 | | |