
Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE NO: 1-188

AIRCRAFT TYPE: SAAB 91B, SAAB 91B-2 and SAAB 91C

SERIAL No:s

AFFECTED: All

SUBJECT: Hartzell propeller blades modell 8428-6. Retirement from service.

BACKGROUND: According to Hartzell Standard Practices Manual 202A it is no longer possible to use the Hartzell model 8428-6 propeller blades. After overhaul of the propeller hub HC-12X20-8() the affected blades can no longer be reinstalled. Further, the manufacturer has no intention to support the airworthiness of these blades. Therefore, the propeller blades model 8428-6 have been removed from the aircraft specifications for SAAB 91B, SAAB91B-2 and SAAB 91C.

REFERENCE DOCUMENTS: TCDS (Aircraft Specification) SAAB 91B, SAAB91B-2 and SAAB 91C. Hartzell Standard Practices Manual 202A.

ACTIONS: Remove from service propeller blades Hartzell model 8428-6.

COMPLIANCE TIME: To be performed at next overhaul of the propeller hub or within 6 months from the effective date of this SAD whichever occurs first.

EFFECTIVE DATE: 14 March 2003

LFS: 2003:30

LUFTFARTSVERKET
Aviation Safety Authority

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register

Mail address	Office address	Telephone number	Fax number	Cable address	Telex address
SE-601 79 NORRKÖPING	Vikboplan 7	+46 11 19 20 00	+46 11 19 25 15	Civilair	64250
SWEDEN	Norrköping		+46 11 19 25 75	Norrköping	