



**Board of Civil Aviation
Sweden**

SAD No 1-002

SWEDISH AIRWORTHINESS DIRECTIVES

Section 1. Swedish manufactured Aeronautical Products

AIRWORTHINESS DIRECTIVE No 1-002

AIRCRAFT TYPE: SAAB-FAIRCHILD 340

SERIAL No:s AFFECTED: 340A-004 and up with engines S/N stated
in below mentioned Service Bulletins

SUBJECT:

- Rework of Compressor Case Lands
- Replacement of the No 4 Bearing
- Introduction of in-flight Engine Performance Trend Monitoring Program

REFERENCE DOCUMENT(S): SAAB-SCANIA AB Service Bulletin SF340-72-002
GENERAL ELECTRIC Service Bulletins (CF7TP)
72-27, 72-28 and 72-31
GENERAL ELECTRIC Operations Engineering
Bulletin No 2

COMPLIANCE TIME: Before any revenue operation

The actions contained in this directive and reference document(s)
have been classified as mandatory for aircraft on Swedish register.

Norrköping September 27, 1984

Board of Civil Aviation
Flight Safety Department

LFS 1984:11

L 1555-2

Mail address

S-601 79 NORRKÖPING

Office address

Vikboplan 11

Telephone No

Nat 011 - 19 20 00
Int + 46 11 - 19 20 00

Directly

Mr Norén 19 20 62
Mr Hedblom 19 20 66

Cable address

Civilair
Norrköping

Telex address

64250