

Section 1. Swedish Manufactured Aeronautical Products

**AIRWORTHINESS DIRECTIVE No:** 1-030

**AIRCRAFT TYPE:** SAAB SF340A (SAAB-FAIRCHILD 340A)

**SERIAL No:s AFFECTED:** 340A-004 through -159

**SUBJECT:** Modification of emergency lighting activation circuit

**BACKGROUND:** A review of emergency lighting activation was initiated by the FAA. The result of the review is that a modification to the system is required to fully meet FAR/JAR 25.812 (f)(3). Loss of both generators will then activate the modified system, also if the ordinary aircraft batteries are live.

**ACTIONS:** Modify the aircraft in accordance with Service Bulletin SAAB SF340-33-028 dated Jan 19, 1989 or later revision

**COMPLIANCE TIME:** This modification must be incorporated not later than May 31, 1989

Norrköping 1989-01-20

LUFTFARTSVERKET  
Flight Safety Department

**LFS:** 1989:3

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.